

District II - Artesia811 S. 1st Street, Artesia, NM 88210

Phone: (575) 748-1283 - Fax: (575)-748-9720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name <i>Spr Energy Partners</i>		API Number <i>30-015-03095</i>	
Property Name <i>Burch Keely unit</i>		Well No. <i>182</i>	

UL - Lot <i>10</i>	Section <i>23</i>	Township <i>17</i>	Range <i>29</i>	Feet from <i>1980</i>	N/E Line <i>0</i>	Feet From <i>1980</i>	E/W Line <i>0</i>	County <i>Eddy</i>
-----------------------	----------------------	-----------------------	--------------------	--------------------------	----------------------	--------------------------	----------------------	-----------------------

Well Status		DATE <i>11-24-21</i>	
TA'D Well YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR INJ ☐ SWI ☒	PRODUCER OIL ☐ GAS ☐

OBSERVED DATA

	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure					<i>180</i>
Flow Characteristics	<i>NO pressure</i>	<i>N/A</i>			
Puff	Y / N	Y / N	Y / N	Y / N	CO2 _____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR _____
Surges	Y / N	Y / N	Y / N	Y / N	GAS _____
Down to nothing	Y / N	Y / N	Y / N	Y / N	If applicable type
Gas or Oil	Y / N	Y / N	Y / N	☒ Y / N	fluid injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK ☒
-------	-------	-------	--------	---

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

Test got some black water from productive casing

Signature: <i>Dan</i>	OIL CONSERVATION DIVISION	
Printed name: Danny Smolik	Entered RBDMS	
Title: Compliance Office O	Re-test	
E-mail Address: danny.smolik@state.nm.us		
Date: <i>11-24-21</i>	Phone: 575-626-0836	
Witness: <i>Brian Thompson</i>		

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 63879

CONDITIONS

Operator: Spur Energy Partners LLC 9655 Katy Freeway Houston, TX 77024	OGRID: 328947
	Action Number: 63879
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	2/4/2022