

District I  
1625 N. French Dr., Hobbs, NM 88240  
Phone: (575) 393-6161 Fax: (575) 393-0720

District II  
811 S 1st Street, Artesia, NM 88210  
Phone: (575) 748-1283 - Fax: (575) 748-9720

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN LTD	API Number 30-025-43282
Property Name NORTH HOBBS G/SA UNIT	Well No. 693

Surface Location

UL -Lot	Section 33	Township 18S	Range 38E	Feet From 1880	N/S Line S	Feet From 1298	E/W Line W	County LEE
---------	---------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

TA'D Well Yes <input checked="" type="radio"/> No	SHUT-IN Yes <input checked="" type="radio"/> No	INJECTOR <input checked="" type="radio"/> INJ SWD	PRODUCING OIL GAS	DATE 9-2-21
--	--	--	----------------------	----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csng	(E) Tubing
Pressure	290	NA	NA	36	1159
<b>Flow Characteristics</b>					CO <sub>2</sub> _____ WTR _____ GAS _____ Type of Fluid _____ Injected for _____ Water Flood if applies _____
Puff	<input checked="" type="radio"/> / N	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	<input checked="" type="radio"/> / N	
Steady Flow	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	
Surges	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	
Down to nothing	<input checked="" type="radio"/> / N	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	<input checked="" type="radio"/> / N	
Gas or Oil	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	
Water	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	

Remarks - Please state for each string (A,V,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Saul Hernandez Saul Hernandez 670 353 5150

Signature: 	OIL CONSERVATION DIVISION
Printed name: JUSTIN SAXON	Entered into RBDMS
Title: SURVEILLANCE LEAD	Re-test
E-mail Address: JUSTIN_SAXON@OXY.COM	
Date:	Phone: 806-215-4197
	Witness:

**District I**  
 1625 N. French Dr., Hobbs, NM 88240  
 Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**  
 811 S. First St., Artesia, NM 88210  
 Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**  
 1220 S. St Francis Dr., Santa Fe, NM 87505  
 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS  
 Action 60642

**CONDITIONS**

Operator: OCCIDENTAL PERMIAN LTD P.O. Box 4294 Houston, TX 772104294	OGRID: 157984
	Action Number: 60642
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

**CONDITIONS**

Created By	Condition	Condition Date
gcordero	None	5/3/2022