Received by OCD: 4/21/2022 1:44:05 1	State of New Mo	exico		Form C-103
Office District I – (575) 393-6161	Energy, Minerals and Natural Resources			ed August 1, 2011
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	N DIVISION	30-025-03874 5. Indicate Type of Lease	
District III – (505) 334-6178	1220 South St. Fra	ncis Dr.	STATE FEE	7
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 8	7505	6. State Oil & Gas Lease N	· 0.
1220 S. St. Francis Dr., Santa Fe, NM 87505				
	ES AND REPORTS ON WELLS	S	7. Lease Name or Unit Agr	reement Name
(DO NOT USE THIS FORM FOR PROPOSA			West Lovington Unit	
DIFFERENT RESERVOIR. USE "APPLICA" PROPOSALS.)	THON FOR PERMIT (FORM C-101) F	OK SUCH	8. Well Number	
	Well Other Injector		13	
2. Name of Operator Chevron USA, Inc.			9. OGRID Number	
3. Address of Operator			241333 10. Pool name or Wildcat	
6301 Deauville Blvd., Midland,	ГХ 79706		W. Lovington Upper San Andr	es
4. Well Location				
Unit Letter F: 1980 feet from	n the North line and 1980 feet fro	om the West line		
Section 4 Township 17S Ra	nge 36E NMPM Lea County			
	11. Elevation (Show whether DE	2, RKB, RT, GR, etc	2.)	
12. Check Appropriate Box to	DF 3895	Panart or Other	Doto	
12. Check Appropriate Box to	indicate Nature of Notice, i	report of Other	Data	
NOTICE OF INT	ENTION TO:	SUE	SSEQUENT REPORT C	OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR		IG CASING
TEMPORARILY ABANDON	CHANGE PLANS		RILLING OPNS. P AND A	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	NT JOB ⊔	PNR
DOWNHOLE COMMINGLE				
OTHER:		OTHER:	TEMPORARILY ABANDO	
13. Describe proposed or comple				
of starting any proposed wor proposed completion or reco	k). SEE RULE 19.15.7.14 NMA	C. For Multiple Co	ompletions: Attach wellbore di	agram of
proposed completion of reco	Chevron USA INC abai	ndoned this well a	as follows:	
1. 04/08/22 MIRU, sqz 35 sx	C cmt @ 4610'-4710'.			
2. 04/11/22 NU BOP, LD tub				
3. 04/12/22 Spot 30 sx C cmt	· 1			
4. 04/13/22 Perf @ 3166', per			8'. Perf @ 2104', perfs press	sured up,
	@ 2154'-1817'. Perf @ 1600'.			
· · · · · · · · · · · · · · · · · · ·	@ 1650'-1410', perf @ 600',	cut csg @ 600'.		
	7, perf @ 336 & 200, perfs pre	ssured up spot 20	00 sv C cmt @ 386'-0 ND F	ROP RDMO
7. 04/17/22 Tag TOC (a) 441	, peri @ 330 & 200, peris pre	ssured up, spot 20	10 SX C CIII (W 300 -0. ND L	or RDMO.
I hereby certify that the information a	bove is true and complete to the b	est of my knowled	ge and belief.	
SIGNATURE Hayes 7	Thibodeaux 4/21/202	2		
Haves Thirodeaux	hibodsaux 4/21/202			
Engineer				
E-mail address: <u>Hayes.thibodeaux@c</u>	281-726-	9683		
E-man address: <u>Hayes.timbodeaux(w/c</u>)	Hevron.com PHONE			
For State Use Only	-1			
APPROVED BY:	TITLE Com	pliance Officer A	DATE 5/23	3/22
Conditions of Approval (if any)				



EMC Ops Summary - External

VEST LOVINGTON UNIT 013 Field Name LOVINGTO		N WEST West Lovington Unit		Area Central			
Business Unit EMC		County/ Parish Lea				Surface UWI 3002503874	
Basic Well Data							
		Original RKB Ele 3,895.00	Elevation (ft) Latitude (°) 32° 51' 56.959" N		Longitude (°) 103° 21' 42.84" W		4" W
Phases				•			
Actual Start Date	Actual E	End Date	Phase 1	Phase 2	Time Lo	g Hrs (hr)	Percent Problem Time (%)
3/31/2022 10:00	3/31/2022 14	4:00	PREP	FAC		4.00	
4/8/2022 08:30	4/8/2022 08:	45	MOB	MOVEON		0.25	
4/8/2022 08:45	4/8/2022 13:	00	ABAN	TBGPULL		4.25	
4/8/2022 13:00	4/13/2022 16	6:00	ABAN	CMTPLUG		25.50	
4/13/2022 16:00	4/19/2022 15	5:00	ABAN	CSGPULL		30.00	
			REST	FAC			
D. J. #. 4. 0/04/0000							

Rpt # 1, 3/31/2022

HSE meeting, hazard hunt, evaluate wellhead corrosion issues, made a plan, hand dig around wellhead, exposed all 3 sets of risers, removed plumbing, made up new assemblies, installed new assemblies, one of the surface sides is to corroded to plumb, communicated with WSR in charge, it was accorded to leave it pen with a side excavated to suck fluids with a vacuum truck, backfilled excavation, load/secured equipment, location is prepped

Rpt # 2, 4/8/2022

Move on. JSA and safety meeting, fill out permits, set up muster areas. R/U. Unload equipment and spot in ancillary trailers. R/U pump, hard lines, and return lines. Check pressures - 50 psi tubing, 0 psi casing, 0 psi intermediate, 0 psi surface casing. Pressure test casing, held 1000 psi for 15 minutes. Establish injection rate - xx bpm @ xxx psi. Request approval from NMOCD to not set CIBP and squeeze below the packer, approval granted. Mix and squeeze 35 sx class C 1.32 yield 14.8 ppg cement and displace TOC to 4610'. Secure well for night and brought pump to yard to repack.

Rpt # 3, 4/11/2022

JSA and safety meeting. Check pressures - 0 psi tubing and casing, slight blow on intermediate, 0 psi surface. Intermediate began to flow clear water after a while of being open. Wait on pump to get to location, clean equipment and tools. N/D larkin flange. N/U 5K 7-1/16" BOP. Pressure test BOP 250 psi 5 minutes, 1000 psi 10 minutes, held good. R/U tubing equipment and work floor. Release AD-1 packer, no issues. TOH 139 IPC 2-3/8" and remove packer. Load racks w/ tubing and TIH 150 jts 2-7/8" tubing. Tag TOC @ 4650'. Secure well for night.

Rpt # 4, 4/12/2022

Operations Summary
JSA and safety meeting. Check pressures - 0 psi tubing and production casing, 50 psi intermediate, 0 psi surface casing. Circulate xx bbls 10 ppg brine.
Pressure test plug 1000 psi for 15 minutes, held good. Spot 25 bbls salt gel MLF. Mix and spot 30 sx class C 1.32 yield 14. 8 ppg cement @ 46500'-4361'.
NMOCD approved no tag required. TOH 22 jts 2-3/8" tubing, EOT @ 3965'. Mix and spot 25 sx class C 1.32 yield 14.8 ppg cement @ 3965'-3725'. L/D 51 jts 2-3/8" tubing, EOT @ 2375'. Bubble test intermediate and surface strings, fail on intermediate, surface string would not fill due to shallow casing hole. Water would fill up in cellars. Secure well for night due to high winds and dusty conditions.

Rpt # 5, 4/13/2022

JSA and safety meeting. Check pressures - 0 psi tubing and production casing, 20 psi intermediate casing, 0 psi surface casing. R/U wireline and make up DP JSA and safety meeting. Check pressures - 0 psi tubing and production casing, 20 psi intermediate casing, 0 psi surface casing. R/U wireline and make up DP gun. Found that wiring to drum was chewed up by rodents. Rewire. RIH and perf @ 3166'. Lay down tools and r/d wireline. Attempt injection, held 2000 psi for 15 minutes w/ no leak off. TIH 27 jts 2-3/8" EOT @ 3216'. Mix and spot 15 bbls salt gel MLF. Recieve approval from NMOCD to spot plug. Mix and spot 60 sx class C 1.32 yield 14.8 ppg cement @ 3216'-2638'. TOH 53 jts 2-3/8" tubing, EOT @ 1548'. Crew lunch break. R/U wireline and make up DP perf gun. RIH and perf @ 2104'. Lay down tools and R/D wireline. Attempt injection, held 1000 psi for 15 minutes w/ no leak off. TIH 19 jts, EOT @ 2154'. Recieve approval from NMOCD to spot plug. Mix and spot 35 sx class C 1.32 yield 14.8 ppg cement @ 2154'-1817'. TOH 69 jts 2-3/8" tubing, no tubing left in hole. R/U wireline and make up DP gun. RIH perf @ 1600'. Lay down tools and R/D wireline. Attempt injection, no injection. Pressured up to 1000 psi but corrosion in wellhead began to wash out and leak down to 500 psi. Bubble test intermediate, was profoundly worse than previous bubble test and took a lot of fluid to fill up. Secure well for night

Rpt # 6, 4/14/2022

Operations Summary
JSA and safety meeting. Check pressures - 0 psi tubing and production casing, 20 psi intermediate casing, 0 psi surface casing. R/U wireline and bond log tool.
RIH w/ log, stack out @ 1772', find bridges at 1320'-1330', 640'-850'. TIH 53 jts 2-3/8" tubing EOT @ 1650'. Recieved approval to spot plug over perfs. Spot 25
sx class C 1.32 yield 14.8 ppg cement @ 1650'-1410. TOH 53 jts tubing. R/U wireline and make up DP perf gun. RIH perf @ 600. Lay down tools. Circulate 10
bbls @ 1.3 bpm 800 psi, broke circulation but was poor circulation. Crew lunch break. Make up cable head and make up jet cutter. RIH w/ jet cutter and cut
casing @ 600'. R/D wireline and break down tools. Circulate 25 bbls 10 ppg brine, circulated out dehydrated mud. Assesed wellhead and flange situation.
Secure well for night.

Rpt # 7, 4/18/2022

JSA and safety meeting. Check pressures - 0 psi all strings, intermediate was on a vacuum. R/D floor and tubing equipment. N/D bird bath and BOP. N/U B1 flange. Cut off bolts from intermediate wellhead. Lift up wellhead and casing was attached to wellhead. Set slips and cut casing at surface. L/D wellhead. R/U workfloor and casing lay down equipment. R/D 19 jts 5-1/2" 14# casing. R/D casing lay down equipment. R/D floor, N/U wellhead and BOP. Pressure test BOP 250 psi 5 minutes, 1000 psi 5 minutes, held good. TIH 21 jts 2-3/8" tubing (50' into stub). Circulate 20 bbls 10 ppg brine. Recieve approval to spot from NMOCD. Mix and spot 45 sx class C 1.32 yield 14.8 ppg cement @ 650'-450' w/ 2% cc. TOH 21 jts tubing. Secure well for night.

Rpt # 8, 4/19/2022

Operations Summary

JSA and safety meeting. Check pressures - 0 psi intermediate and surface. TIH tag TOC @ 441'. TOH, lay down tubing. Bubble test surface and intermediate both pass. R/U wireline and make up 5 spf DP gun. RIH & perf @ 336'. Attempt injection, pressured up, no communication. R/U wireline and make up 5 spf DP
gun. RIH & perf @ 200' per verbal guidance from NMOCD (K. Fortner). Attempt injection, pressured up, no communication. Approved to spot to cover perfs and
bring to surface. TIH 12 jts 2-3/8" tubing, EOT @ 386'. Mix and spot 100 sx from 386'-0' and shut in and squeeze away +100 sx until cement returns came from
ground around wellhead (200 sx total for plug). TOH L/D 12 jts tubing, R/D tubing equipment and workfloor. N/D BOP. N/U B1 flange. R/D rig and load
equipment on flatbed. R/D cement equipment, pump, and hardlines. Move out to WLU 29.

Company Confidential - Restricted

Released to Imaging: 5/24/2022 7:12:02 AM


Page 1/1

Report Printed: 4/21/2022

As plugged WBD

Created:	04/24/19	By:	
Updated:		By:	
Lease:	Wes	st Lovington	Unit
Field:	Wes	st Lovington	Unit
Surf. Loc.:	1980	FNL & 1980	FWL
Bot. Loc.:			
County:	Lea	St.:	NM
Statuc			

Well #:	13	St. Lse:	
API		30-025-03874	
Unit Ltr.:	F	Section:	4
TSHP/Rng:		17S-36E	
Unit Ltr.:		Section:	
TSHP/Rng:			
Directions:		Lovington, NM	
Chevno:		FA5021	



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

COMMENTS

Action 100651

COMMENTS

Operator:	OGRID:
CHEVRON U S A INC	4323
6301 Deauville Blvd	Action Number:
Midland, TX 79706	100651
Γ.	Action Type:
	[C-103] Sub. Plugging (C-103P)

COMMENTS

C	reated By	Comment	Comment Date
	plmartinez	DATA ENTRY PM	5/24/2022

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 100651

CONDITIONS

Operator:	OGRID:
CHEVRON U S A INC	4323
6301 Deauville Blvd	Action Number:
Midland, TX 79706	100651
	Action Type:
	[C-103] Sub. Plugging (C-103P)

CONDITIONS

Created By	Condition	Condition Date
kfortne	Need C103Q and marker pics to release	5/23/2022