

Distorted 1
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Chevron USA, Inc.		Operator Name		API Number	
Vacuum Blower West Unit		Property Name		30-025-31884	
				Well No.	
				107	

Surface Location									
UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet from	E/W Line	County
D	36	105	34E		183	F2L	931	F6L	LEA

Well Status						DATE
TA'D Well	SHUT-IN	INJECTOR	PRODUCER			
YES	(NO)	YES	(NO)	(INJ)	SWD	OIL GAS
						6-14-21

OBSERVED DATA

	(ASIDE) (1)	(B) (2)	(C) (3)	(D) (4)	(E) (5)
Pressure	0	N/A	N/A	0	1500
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.	
Signature:	
Printed name: Jesus Romero	
Title: Field Specialist	
E-mail Address: jrw@chevron.com	
Date: 6-14-21	Phone: 575-988-1256
Witness:	
OIL CONSERVATION DIVISION	
Entered into RBDMS	
Re-test	
K 7	

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 136569

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 136569
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	8/23/2022