

South District – Artesia

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name XTO ENERGY, INC.	³ API Number 30-015-28594
Property Name AVALON DELAWARE UNIT	Well No. 503

⁷ Surface Location

UL - Lot B	Section 31	Township 20S	Range 28E		Feet from 43	N/S Line N	Feet From 1458	E/W Line E	County EDDY
---------------	---------------	-----------------	--------------	--	-----------------	---------------	-------------------	---------------	----------------

Well Status

TA'D Well	SHUT-IN	INJECTOR	PRODUCER	DATE
YES NO	YES NO	INJ SWD	OIL GAS	5-10-22

OBSERVED DATA


	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure	40	0			60
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 _____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR _____
Surges	Y / N	Y / N	Y / N	Y / N	GAS _____
Down to nothing	Y / N	Y / N	Y / N	Y / N	If applicable type
Gas or Oil	Y / N	Y / N	Y / N	Y / N	fluid injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

Test Good

Signature: 	OIL CONSERVATION DIVISION
Printed name: Dan Smolik	Entered RBDMS
Title: Compliance Officer	Regulatory Analyst
E-mail Address: cassie.evans@exxonmobil.com	Re-test
Date: 5-10-22	Phone:
	Witness:

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 130188

CONDITIONS

Operator: XTO ENERGY, INC 6401 Holiday Hill Road Midland, TX 79707	OGRID: 5380
	Action Number: 130188
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	9/16/2022