



BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10/26/22 Operator Crownquest Co. Reddy Production API #30-039-24143

Property Name Chacon Jct. Ap. A Well No. 11 Location: Unit C Section 14 Township 23N Range 3W

Well Status (Shut-In or Producing) Initial PSI: Tubing 30 Intermediate 0 Casing 30 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	0	30	0	30
10 min	0	0	30	0	30
15 min	0	0	30	0	30
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	none	none
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

No psi on Intermediate / Bradenhead Blow down within
5 sec. / Pumping Well

By [Signature]
Lease Manager
(Position)

Witness _____

E-mail address ttixier@crowquest.com

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 154671

CONDITIONS

Operator: RODDY PRODUCTION CO INC 4001 N. BUTLER, BLDG 7101 Farmington, NM 87401	OGRID: 36845
	Action Number: 154671
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
mkuehling	None	11/28/2022