



BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10/27/22 Operator Crown Quest / Reddy Production API # 30-043-20427

Property Name Chalon Tr. Ap. D Well No. 105 Location: Unit D Section 36 Township 23N Range 3W

Well Status (Shut-In or Producing) Initial PSI: Tubing 41 Intermediate NA Casing 42 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>NA</u>	<u>42</u>	<u>1</u>	<u>1</u>
10 min	<u>0</u>	<u>NA</u>	<u>42</u>	<u>1</u>	<u>1</u>
15 min	<u>0</u>	<u>NA</u>	<u>42</u>	<u>1</u>	<u>1</u>
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u>none</u>	<u>NA</u>
Surges	<u>1</u>	<u>1</u>
Down to Nothing	<u>1</u>	<u>1</u>
Nothing	<u>1</u>	<u>1</u>
Gas	<u>1</u>	<u>1</u>
Gas & Water	<u>1</u>	<u>1</u>
Water	<u>1</u>	<u>1</u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS: No psi. / Pumping Well

By Jim F.
Lease Manager
(Position)

Witness _____

E-mail address ttixier@crowquest.com

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 154675

CONDITIONS

Operator: RODDY PRODUCTION CO INC 4001 N. BUTLER, BLDG 7101 Farmington, NM 87401	OGRID: 36845
	Action Number: 154675
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
mkuehling	None	11/28/2022