



## Surface Reclamation Complete Report

**Well Name:** RICHARD KNOB AEX STATE #002

**API:** 30-015-26073

**Well Location:** K-34-17S-24E

**Surface Owner:** STATE OF NEW MEXICO

**Reclamation Complete Date:** 5/19/22

**Total Acres reclaimed:** 2.75 acres

### **Seed Mix:**

Mix	Species	lb/acre (Drilled)	lb/acre (Broadcast)
NMSLO - Loamy (L)	Black Grama	2.0	4.0
"	Blue Grama	2.0	4.0
"	Sideoats Grama	2.0	4.0
"	Sand Dropseed	1.0	2.0
"	Alkali Sacaton	2.5	5.0
"	Little Bluestem	2.5	5.0

Weights should be as pounds of pure live seed.

### Note:

EOG will conduct an annual surface reclamation monitoring field visit in 2023 to determine if successful vegetation regrowth is established.

### 3<sup>RD</sup> party riser on NE side of pad





Date & Time: Thu Sep 22 13:36:12 MDT 2022  
Position: 032.79078°N / 104.57840°W  
Altitude: 3749ft  
Datum: NORTH AMERICAN 1983, CONUS  
Azimuth/Bearing: 229° S49W 4071mils (True)  
Zoom: 1X  
I. Rios





On-Site Regulatory Reclamation Inspection							Date: <u>9/22/2022</u>	
Site Name: <u>Michael Monb AEX State #002</u>								
API Number: <u>30-0 15 26073</u>		Plug Date: <u>12/8/2021</u>		Program: <u>(Initial)</u>		Annual		
Was this the last remaining or only well on the location?							YES	NO
Are there any abandoned pipelines that are going to remain on the location?							<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that are going to remain on location?							<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
If any production equipment or structure (including 3rd party) is to remain on location, please specify. <u>3rd Party Riser on N-E Side of pad</u>								
<b>Site Evaluation</b>								
Recontoured back to original State/Topsail Replaced							YES	NO
Have the rat hole and cellar been filled and leveled?							<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Have the cathodic protection holes been properly abandoned & reclaimed?							<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Rock or Caliche Surfacing materials have been removed?							<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Section Comments:</b>								
All Facilities Removed for Final Reclamation								
Have all of the pipelines & production equipment been cleared? (other than the listed above)							<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Has all of the required junk and trash been cleared from the location?							<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Have all of the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level?							<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Have all of the required metal bolts and other materials have been removed?							<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Have all the required portable bases been removed?							<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Section Comments:</b>								
<b>Dry Hole Marker</b>								
Has a steel marker been installed per COA requirements?							YES	NO
Check One: <input type="checkbox"/> Buried <input checked="" type="checkbox"/> Above Ground							<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
DHM Info	Operator Name	Lease Name & Number	UL-S-T-R	Qtr Section (Footage)	API #	Federal Lease # (Federal Only)		
Met	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<u>NA</u>		
Not Met								
<b>Free of Oil or Salt Contaminated Soil</b>								
Have all the required pits been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?							YES	NO
Have all other environmental concerns been addressed as per OCD rules?							<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
If any environmental concerns remain on the location, please specify.								
<b>Abandoned Pipelines</b>								
Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19. 15. 35. 10 NMAC).							YES	NO
Have all fluids have been removed from any abandoned pipelines?							<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Have all abandoned pipelines been confirmed to NOT contain additional regulated NORM, other than that which accumulated under normal operation?							<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Have all accessible points of abandoned pipelines been permanently capped?							<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Section Comments:</b>								
<b>Last Remaining or Only Well on the Location</b>								
Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.							YES	NO
Have all electrical service poles and lines been removed from the location?							<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Is there any electrical utility distribution infrastructure that is remaining on the location?							<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?							<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Have all the retrievable pipelines, production equipment been removed from the location?							<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Has all the junk and trash been removed from the location?							<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Section Comments:</b>								
<b>Environmental Only- Do not have to be met to pass inspection</b>								
This section corresponds with questions on the Reclamation Inspection Form in Environmental but not related to NMOC forms.							Met	Not Met
Free of Noxious or Invasive Weeds? (Note species or treatment in remarks)							<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Site Stability? Erosion controls in place (if necessary) & working.							<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Signs of seeding completion? (Broadcast/Drilled)							<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Revegetation Success as compared to background? Met >75%.							<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Circle One: <u>0%</u> 25% 50% 75% 100%							<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Adequate Reclamation Fence installed?							<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Section Comments:</b>								
Additional Findings or Comments: <u>Reclamation Gate has been put in place to prevent Traffic thru Road</u>								
Inspector: <u>Ego. P...</u>								
<div style="display: flex; justify-content: space-between;"> <div> <b>Picture Checklist:</b>  <input checked="" type="checkbox"/> DHM <input checked="" type="checkbox"/> Background <input checked="" type="checkbox"/> 3rd Party Equipment <input type="checkbox"/> Contamination <input type="checkbox"/>  <input checked="" type="checkbox"/> Site Corners <input type="checkbox"/> Access Road <input type="checkbox"/> EOG Equipment <input type="checkbox"/> Trash/Junk <input type="checkbox"/> </div> <div> <input type="checkbox"/> READY FOR FAN SUBMITTAL  <input type="checkbox"/> NEEDS FURTHER REVIEW  <b>Inspection Result</b>  <input checked="" type="radio"/> PASS <input type="radio"/> FAIL         </div> </div>								

On-Site\_Inspection\_Form v1.xlsx

7/7/202

**District I**

1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**

811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**

1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

DEFINITIONS

Action 148970

## DEFINITIONS

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 148970
	Action Type: [C-103] Sub. Release After P&A (C-103Q)

## DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- lease and well location, hereinafter "location";
- flowlines or pipelines, hereinafter "pipelines";
- and non-retrieved or abandoned, hereinafter "abandoned".

**District I**

1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**

811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**

1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS

Action 148970

**QUESTIONS**

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 148970
	Action Type: [C-103] Sub. Release After P&A (C-103Q)

**QUESTIONS**

Subsequent Report of: Location Ready For OCD Inspection After P&A	
Was this the last remaining or only well on the location	Yes
Are there any abandoned pipelines that are going to remain on the location	No
Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that is going to remain on the location	Yes
If any production equipment or structure is to remain on the location, please specify	3rd Party riser on Northeast side of pad.

**Site Evaluation**

Please answer all the questions in this group.

Have all the required pits been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan	Yes
Have the rat hole and cellar been filled and leveled	Yes
Have the cathodic protection holes been properly abandoned	Yes
Has a steel marker, at least 4 inches in diameter and at least 4 feet above ground level, been set in concrete	Yes
The (concrete-set) steel marker shows: Must attach marker photograph(s). *	<b>THE OPERATOR NAME, LEASE NAME AND WELL NUMBER AND LOCATION, INCLUDING UNIT LETTER, SECTION, TOWNSHIP AND RANGE, SHALL BE WELDED, STAMPED OR OTHERWISE PERMANENTLY ENGRAVED INTO THE MARKER'S METAL.</b>
Has the location been leveled as nearly as possible to original ground contour	Yes
Have all the required pipelines and other production equipment been cleared	Yes
Has all the required junk and trash been cleared from the location	Yes
Have all the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level	Yes
Have all the required metal bolts and other materials have been removed	Yes
<b>Poured onsite concrete bases do not have to be removed.</b>	
Have all the the required portable bases been removed	Yes
Have all other environmental concerns have been addressed as per OCD rules	Yes
If any environmental concerns remain on the location, please specify	Not answered.

\* Proof of the site marker (photograph) is required.

Please submit any other site photographs that would assist in documenting the above answers, site features, additional concerns, or other nearby / remaing structures and equipment.

**District I**

1625 N. French Dr., Hobbs, NM 88240  
 Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**

811 S. First St., Artesia, NM 88210  
 Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**

1000 Rio Brazos Rd., Aztec, NM 87410  
 Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505  
 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 148970

**QUESTIONS (continued)**

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 148970
	Action Type: [C-103] Sub. Release After P&A (C-103Q)

**QUESTIONS**

<b>Abandoned Pipelines</b>	
<i>Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19.15.35.10 NMAC).</i>	
Have all fluids have been removed from any abandoned pipelines	<i>Not answered.</i>
Have all abandoned pipelines been confirmed to <b>NOT</b> contain additional regulated NORM, other than that which accumulated under normal operation	<i>Not answered.</i>
Have all accessible points of abandoned pipelines been permanently capped	<i>Not answered.</i>

<b>Last Remaining or Only Well on the Location</b>	
<i>Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.</i>	
Have all electrical service poles and lines been removed from the location	Yes
Is there any electrical utility distribution infrastructure that is remaining on the location	No
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan	Yes
Have all the retrievable pipelines, production equipment been removed from the location	Yes
Has all the junk and trash been removed from the location	Yes

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

ACKNOWLEDGMENTS  
  
Action 148970

ACKNOWLEDGMENTS

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 148970
	Action Type: [C-103] Sub. Release After P&A (C-103Q)

ACKNOWLEDGMENTS

<input checked="" type="checkbox"/>	I hereby certify that all the work has been completed for this location and the site is ready for an OCD scheduled inspection.
-------------------------------------	--



**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS  
  
Action 148970

**CONDITIONS**

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 148970
	Action Type: [C-103] Sub. Release After P&A (C-103Q)

**CONDITIONS**

Created By	Condition	Condition Date
gcordero	None	10/13/2022