

# **Surface Reclamation Complete Report**

Well Name: DAYTON FG #001

**API**: 30-015-21721

Well Location: B-28-18S-26E

**Surface Owner**: EOG

**Reclamation Complete Date:** 11/28/22

**Total Acres reclaimed:** 1 acres

# **Seed Mix**:

Mix	Species	lb/acre (Drilled)	lb/acre (Broadcast)
NMSLO - Loamy (L)	Black Grama	2.0	4.0
	Blue Grama	2.0	4.0
	Sideoats Grama	2.0	4.0
"	Sand Dropseed	1.0	2.0
"	Alkali Sacaton	2.5	5.0
"	Little Bluestem	2.5	5.0
"	Firewheel (Gaillardia)	1.0	2.0
"	Fourwing Saltbush	1.0	2.0
· · ·	Common Winterfat	0.5	1.0
Weights should be as pounds of pure liv	e seed.		

# Note:

EOG will conduct an annual surface reclamation monitoring field visit in 2023 to determine if successful vegetation regrowth is established.





On-Site Regulat	ory Reclamation	Inspection		Date:	12 / 30	) / 2022			
Site Name:	Dayton FG #001								
API Number:	30-0_15 - 21721	1 Plug I	Date: <u>11 / 2</u>	9 /2021	Program:		Monitoring	WEE	NO
Was this the last remain	ng or only well on the loa	cation?				Final	Corrective	YES	NO
Are there any abandone	•		ation?						×
Is there any production	equipment or structure (r	not including steel me	rker, poured onsite concre	te bases, or pipelines) that	are going to	remain on lo	cation?		×
If any production equipr	nent or structure (includi	ng 3rd party) is to rer	nain on location, please spe	ecity.					
Site Evaluation									
Recontoured back to	original State/Topsoil	Replaced						YES	NO
Have the rat hole and ce			_					×	
Have the cathodic prote Rock or Caliche Surfacing			ned?					×	
Section Comments:	,								
All Facilities Removed	for Final Reclamation	ı							
Have all of the pipelines	& production equipment	been cleared? (other	than the listed above)					×	
Has all of the required ju								×	
	enchors, dead men, tie do metal bolts and other ma		been out off at least two fer noved?	et below ground level?				×	
Have all the required po								×	
Section Comments:									
Dry Hole Marker								YES	NO
Has a steel marker been	installed per COA require	ements?		Check One	☐ Burio	ıd 🛭	Above Ground	×	
		Lease Name & Num	iher	Τ '			Federal Lease #		
DHM Info	Operator Name		UL-S-T-R	Otr Section (Footage)	_	PI#	(Federal Only)		
Met Not Met	×	×	×	×	,	×			
Free of Oil or Salt Con	taminated Soil							YES	NO
Have all the required pit	been remediated in con	npliance with OCD ru	les and the terms of the Op	erator's pit permit and clo	sure plan?			×	
Have all other environm	ental concerns been addr	essed as per OCD rul	<b>5</b> ?					×	
If any environmental cor	cerns remain on the loca	stion, please specify.							
Abandoned Pipelines								VEC	NO
	wers in this group, if any removed from any aban		ibandoned (in accordance w	nth 19. 15. 35. 10 NMAC).				YES	NO
			al regulated NORM, other	than that which accumulat	ted under no	rmal operatio	on?	$\overline{}$	
Have all accessible points of abandoned pipelines been permanently capped?					,				
Section Comments:									
Last Remaining or On	•		is no longer going to be an	v well or facility remaining	at this locat	ion		YES	NO
Have all electrical service				,				×	
Is there any electrical ut	lity distribution infrastru	cture that is remainin	g on the location?						×
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?			×						
Have all the retrievable pipelines, production equipment been removed from the location?  Has all the junk and trash been removed from the location?			×						
Section Comments:								~	
iEnvironmental Only-	Do not have to be met to	pass inspection							
			Form in iEnvironmental but	not related to NMOCD for	ms.			Met	Not Met
Free of Naxious or Invasi			arks)					×	
Site Stability? Erosion co Signs of seeding complet		ry) a working.						×	
Revegetation Success as		1? Met >75%.	Circle One	: 0% 25%	50%	75%	100%	_^	×
Adequate Reclamation F	ence installed?							×	
Section Comments:									
Additional Findings or	Comments:								
Inspector: Igor Ric	s						READY FOR FAI		
				_				on Result	
Picture Checklist:		Background Access Road	☐ 3rd Party Equipment ☐ EOG Equipment	☐ Contamination ☐ . ☐ Trash/Junk ☐ .			PASS	○ F#	AIL .

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

DEFINITIONS

Action 174741

### **DEFINITIONS**

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	174741
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

### **DEFINITIONS**

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- lease and well location, hereinafter "location";
- flowlines or pipelines, hereinafter "pipelines";
- and non-retrieved or abandoned, hereinafter "abandoned".

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III 1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

QUESTIONS

Action 174741

QUESTIONS				
Operator: EOG RESOURCES INC	OGRID: 7377			
P.O. Box 2267 Midland, TX 79702	Action Number: 174741			
	Action Type: [C-103] Sub. Release After P&A (C-103Q)			
QUESTIONS				
Subsequent Report of: Location Ready For OCD Inspection After P&A				
Was this the last remaining or only well on the location	Yes			
Are there any abandoned pipelines that are going to remain on the location	No			
Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that is going to remain on the location	No			
If any production equipment or structure is to remain on the location, please specify	Not answered.			
Site Evaluation				
Please answer all the questions in this group.				
Have all the required pits been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan	Yes			
Have the rat hole and cellar been filled and leveled	Yes			
Have the cathodic protection holes been properly abandoned	Yes			
Has a steel marker, at least 4 inches in diameter and at least 4 feet above ground level, been set in concrete	Yes			
The (concrete-set) steel marker shows:  Must attach marker photograph(s). *	THE OPERATOR NAME, LEASE NAME AND WELL NUMBER AND LOCATION, INCLUDING UNIT LETTER, SECTION, TOWNSHIP AND RANGE, SHALL BE WELDED, STAMPED OR OTHERWISE PERMANENTLY ENGRAVED INTO THE MARKER'S METAL.			
Has the location been leveled as nearly as possible to original ground contour	Yes			
Have all the required pipelines and other production equipment been cleared	Yes			
Has all the required junk and trash been cleared from the location	Yes			
Have all the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level	Yes			
Have all the required metal bolts and other materials have been removed	Yes			
Poured onsite concrete bases do not have to be removed.				
Have all the the required portable bases been removed	Yes			
Have all other environmental concerns have been addressed as per OCD rules	Yes			
If any environmental concerns remain on the location, please specify	Not answered.			

Please submit any other site photographs that would assist in documenting the above answers, site features, additional concerns, or other nearby / remaing structures and equipment.

\* Proof of the site marker (photograph) is required.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

QUESTIONS, Page 2

Action 174741

QUESTIONS	(continued)
QUESTIONS:	COHUHUCU <i>i</i>

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	174741
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

#### QUESTIONS

Abandoned Pipelines	
Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19.15.35.10 NMAC).	
Have all fluids have been removed from any abandoned pipelines	Not answered.
Have all abandoned pipelines been confirmed to <u>NOT</u> contain additional regulated NORM, other than that which accumulated under normal operation	Not answered.
Have all accessible points of abandoned pipelines been permanently capped	Not answered.

Last Remaining or Only Well on the Location		
Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.		
Have all electrical service poles and lines been removed from the location	Yes	
Is there any electrical utility distribution infrastructure that is remaining on the location	No	
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan	Yes	
Have all the retrievable pipelines, production equipment been removed from the location	Yes	
Has all the junk and trash been removed from the location	Yes	

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

# **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

ACKNOWLEDGMENTS

Action 174741

## **ACKNOWLEDGMENTS**

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	174741
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

### **ACKNOWLEDGMENTS**

I hereby certify that all the work has been completed for this location and the site is ready for an OCD scheduled inspection.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 174741

# **CONDITIONS**

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	174741
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

### CONDITIONS

Created By		Condition Date
gcordero	None	1/13/2023