

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

Well Name: CENTRAL BISTI UNIT Well Location: T25N / R12W / SEC 7 / County or Parish/State: SAN

SWNE / 36.417435 / -108.14975 JUAN / NM

Well Number: 64 Type of Well: OIL WELL Allottee or Tribe Name:

UNIT NMNM78386X

US Well Number: 3004505489 Well Status: Abandoned Operator: DJR OPERATING LLC

Subsequent Report

Sundry ID: 2717096

Type of Submission: Subsequent Report

Type of Action: Plug and Abandonment

Date Sundry Submitted: 02/23/2023 Time Sundry Submitted: 07:11

Date Operation Actually Began: 01/19/2023

Actual Procedure: The subject well was Plugged & Abandoned on 01/19/2023 per the attached End of Well Report, As Plugged Wellbore Diagram, and Marker.

SR Attachments

Actual Procedure

00_EOW_BLM_Submittal_20230222070844.pdf

Well Location: T25N / R12W / SEC 7 / County or Parish/State: SAN 200

SWNE / 36.417435 / -108.14975

Well Number: 64 Type of Well: OIL WELL Allottee or Tribe Name:

Lease Number: NMSF078056 Unit or CA Name: CENTRAL BISTI Unit or CA Number:

UNIT NMNM78386X

JUAN / NM

US Well Number: 3004505489 Well Status: Abandoned Operator: DJR OPERATING LLC

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: MARYA COLLARD Signed on: FEB 23, 2023 07:11 AM

Name: DJR OPERATING LLC

Title: Regulatory Technician

Street Address: 1 ROAD 3263

City: AZTEC State: NM

Phone: (505) 634-6722

Email address: MCOLLARD@DJRLLC.COM

Field

Representative Name:

Street Address:

City: State: Zip:

Phone:

Email address:

BLM Point of Contact

BLM POC Name: KENNETH G RENNICK **BLM POC Title:** Petroleum Engineer

BLM POC Phone: 5055647742 BLM POC Email Address: krennick@blm.gov

Disposition: Accepted **Disposition Date:** 02/23/2023

Signature: Kenneth Rennick

DJR Operating, LLC
P&A End of Well Report
Central Bisti Unit 64
API # 30-045-05489
SW/NE Unit G. Sec 7, T25N, R12W

San Juan County, NM Spud Date: 7-26-1956 Plug Date: 1-26-2023

NOTE: This well was originally cased with 5 $\frac{1}{2}$ " production casing. The 5 $\frac{1}{2}$ " casing developed leaks and 4 $\frac{1}{2}$ " FJ casing was run inside the 5 $\frac{1}{2}$ " casing to a depth of 3965' and cemented in place.

12-16 & <u>17-2020</u>:

MIRU rig and equipment. Pull rods and pump. Remove tubing. Convert well for swab production via casing swab.

Release rig.

1-19-2023:

MIRU rig and equipment. SICP = 110 psi, BHP = 2 psi. Run WL gauge ring to 3900'. POOH. 1-20-2023:

TIH with 2 3/8" workstring. Tagged fill at 4905'.

P&A Plug 1: Gallup perforations and formation top: Mix and pump blind plug of 42 sx from 4898'. WOC. Tagged Plug 1 at 4669'. PT casing, did not test.

Run CBL from 4300' to surface. POOH.

TIH to 3888'.

P&A Plug 2: Mancos formation top: Mix and pump balanced plug of 15 sx from 3888'. Pull up hole. WOC.

1-23-2023:

TIH, tagged Plug 2 at 3625'. TOOH.

RIH, perforate holes at 1987'. POOH.

TIH with retainer, set retainer at 1952'. Establish rate.

P&A Plug 3: Mesa Verde formation top: Mix and pump plug of 47 sx, (31 sx outside, 4 sx under retainer and 12 sx above retainer). Pull up hole. WOC.

TIH, tagged Plug 3 at 1785'. TOOH.

RIH, perforate holes at 1579', POOH.

TIH with retainer, set retainer at 1523'. Establish rate.

P&A Plug 4: Chacra formation top: Mix and pump plug of 47 sx, (31 sx outside, 4 sx under retainer and 12 sx above retainer). Pull up hole. WOC.

1-24-2023:

TIH, tagged Plug 4 at 1372'. TOOH.

RIH, perforate holes at 1274', POOH.

TIH with retainer, set retainer at 1230'. Establish rate.

P&A Plug 5: Pictured Cliffs formation top: Mix and pump plug of 47 sx, (31 sx outside, 4 sx under retainer and 12 sx above retainer). Pull up hole. WOC.

Identified casing leak under BOP. Repaired leak. PT casing, good test. Pictured Cliffs TOC established at 1072'. TOOH.

RIH, perforate holes at 944', POOH.

TIH with retainer, set retainer at 915'. Establish rate.

P&A Plug 6: Fruitland formation top: Mix and pump plug of 45 sx, (31 sx outside, 4 sx under retainer and 10 sx above retainer). TOOH.

RIH, perforate holes at 617', POOH.

Establish rate down casing and out BH.

P&A Plug 7: Kirtland and Ojo Alamo formation tops, surface casing shoe to surface: Mix and pump plug of 300 sx down casing and out BH. SDFN. 1-25-2023:

ND BOP. TOC in $4\frac{1}{2}$ " casing at 53'. Pumped in $4\frac{1}{2}$ " casing to determine if flow could be achieved out BH, were able to pump down $4\frac{1}{2}$ " casing at 2.5 bpm, no flow out of BH but there was flow out of the $4\frac{1}{2}$ " x $5\frac{1}{2}$ " annulus. Approval from BLM and NMOCD to perforate at 52' and test for communication between the various casing strings.

Perforated the 4 $\frac{1}{2}$ " and 5 $\frac{1}{2}$ " casings at 52'. Pumped down casing with flow out 4 $\frac{1}{2}$ " x 5 $\frac{1}{2}$ " annulus but no flow out BH.

P&A Plug 8: Mix and pump plug of 33 sx, (25 sx down 4 $\frac{1}{2}$ " casing with 4 $\frac{1}{2}$ x 5 $\frac{1}{2}$ " annulus closed. Mixed and pumped 8 sx down 4 $\frac{1}{2}$ " x 5 $\frac{1}{2}$ " annulus). SDFN. 1-26-2023:

Cut off WH. TOC in 4 ½" casing and in 4 ½" x 5 ½" annulus at surface, 4' in 8 5/8" surface casing. Install P&A marker. Top off casings and cellar with 32 sx. Released rig.

All cement used was Class G mixed at 15.8 ppg, yield 1.15 cuft/sx

Regulatory representative: Wanda Weatherford, BLM, and Monica Kuehling, NMOCD via phone.

GPS Coordinates: Lat; 36.4175 N, Long; 108.150556 W

DJR Operating, LLC
P&A End of Well Report
Central Bisti Unit 64
API # 30-045-05489
SW/NE Unit G. Sec 7, T25N, R12W
San Juan County, NM
Spud Date: 7-26-1956

Spud Date: 7-26-1956 Plug Date: 1-26-2023



End of Well Report DJR Operating, LLC Central Bisti Unit 64

API # 30-045-05489 SW/NE, Unit G, Sec 7, T25N, R12W San Juan County, NM

GL 6274' KB 6283' Spud Date 7/26/1956

SURF CSG Hole size 12.25" FORMATION TOPS Csg Size: 8.625" 24# Nacimiento Surface Wt: N/A Ojo Alamo Grade: N/A 8.097" Kirtland 567' 894' Depth 352' Fruitland Pictured Cliffs 1224' 0.3575 Csg cap ft3: TOC: Circulated to surface Chacra 1529' Mesa Verde 1937' Mancos 3838' Gallup 4732' PROD CSG ∞ Hole size 7.875" Csg Size: 5.5" Wt: 14# Grade: J-55 4 950" ID. Depth 4989' Csg cap ft3: 0.137 Csg/Csg Ann ft3: 0.1926 Csg/OH cap ft3: 0.1733 Annular TOC: N/A 4.5" FL4S in 5.5" 15# 3965' ID. 10.23# K-55 4.000" Csg cap ft3: 0.0872 4 1/2" FJ casing set inside 5 1/2" casing and cemented in place Perfs 4842-4930' COTD 4930' PBTD 4950' TD 4990'

1-26-2023: Cut off WH, TOC in 4 1/2" and 4 1/2" x 5 1/2" annulus at surface and 4' in surface casing. Install P&A marker. Top off with 32 sx.

1-25-2023: Plug 7: TOC in 4 1/2" casing at 53'. Approval from BLM and NMOCD to perforate 4 1/2" casing at 52' and test for communication. Perforated at 52'. Pumped down 4 1/2" casing, established injection rate, no flow out BH but flow out 4 1/2" x 5 1/2" annulus. Mixed and pumped 25 sx down 4 1/2" casing, then pumped 8 sx into 4 1/2" x 5 1/2" annulus.

1-24-2023: Plug 6: Kirtland, Ojo Alamo, surface casing shoe to surface: Perforate holes at 617'. Mix and pump plug of 300 sx down casing and out BH. Cement returns out BH.

1-24-2023: Plug 6: Fruitland: Perforate holes at 944'. Set CR at 915'. Mix and pump plug of 45 sx from 944' to 783', (31 sx outside, 4 sx below and 12 sx above CR).

1-24-2023: Plug 5: Pictured Cliffs: Perforate holes at 1274'. Set CR at 1230'. Mix and pump plug of 47 sx, (31 sx outside, 4 sx below and 12 sx above CR). WOC. Repair WH. PT casing, good test.

1-23-2023: Plug 4: Chacra: Perforate holes at 1579'. Set CR at 1523'. Mix and pump plug of 47 sx, (31 sx outside, 4 sx below and 12 sx above CR). WOC. 1-24-2023, tagged Plug 4 at 1372'.

1-23-2023: Plug 3: Mesa Verde: Perforate holes at 1987'. Set CR at 1952'. Mix and pump plug of 47 sx, (31 sx outside, 4 sx below and 12 sx above CR). WOC. Tagged Plug 3 at 1785'.

1-202-2023: Plug 2: Mancos: Mix and spot a balanced plug of 15 sx from 3888'. WOC. 1-23-2023, tagged Plug 2 at 3625'.

1-20-2023: Ran CBL from 4300' to surface. TOC. Variable due to 4 1/2" FL4S cemented inside 5 1/2" casing.

1-20-2023, PT casing, did not test. 1-20-2023: Plug 1: Gallup perfs and top: Mix and spot blind plug of 42 sx from

4898'. WOC. Tagged Plug 1 at 4669'.

1-20-2023: Tagged fill at 4905'

All cement used was Class G mixed at 15.8 ppg, yield 1.15 cuft/sx Regulatory representative; Wanda Weatherford, BLM and Monica Kuehling, NMOCD via phone GPS Coordinates: Lat; 36.4175 N, Long; 108.150556 W

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 193424

CONDITIONS

Operator:	OGRID:
DJR OPERATING, LLC	371838
1 Road 3263	Action Number:
Aztec, NM 87410	193424
	Action Type:
	[C-103] Sub. Plugging (C-103P)

CONDITIONS

Created By	Condition	Condition Date
mkuehling	daily string pressures not noted - well plugged 1/26/23	3/24/2023