



**Surface Reclamation Complete Report
&
Annual Surface Reclamation Monitoring Report**

Well Name: STARR 34 FEE #001H

API: 30-005-64018

Well Location: P-34-15S-24E

Surface Owner: MENEFEER FARMS, LLC

Reclamation Complete Date: 4/7/21

Reclamation Annual Monitoring Date: 5/10/22

Total Acres reclaimed: 0.25

Seed Mix: Do not seed per work plan/land owner.

Note:

EOG will conduct an annual surface reclamation monitoring field visit in 2023 to determine if successful vegetation regrowth is established.





Surface Owner Approval of Reclamation completed with Well P&A

Well Name: Starr 34 Fee #001H

API: 30-005-64018


Location: SE/4SE/4 being approximately 0.25 acres in total area.

Section: 34
Township: 15 South
Range: 24 East
County: Chaves

Surface owner: Dwight Menefee for Menefee Farms, LLC
446 W. Pearson Road
Lake Arthur, NM 88253

I hereby agree that EOG Resources, Inc. has completed all surface reclamation activities to meet our requirements as surface owner for the above noted well. Surface Landowner has two (2) piles of cow manure that are both located on the pad and want left in place so therefore EOG will not be responsible for clean-up of same. See attached pictures.

Surface Owner Name: Dwight Menefee for Menefee Farms, LLC

Surface Owner Signature:  for Menefee Farms, LLC

EOG Representative Name: Keith Kistner

EOG Representative Signature: 

Dated: 2-16-23

| On-Site Regulatory Reclamation Inspection | | Date: | 3 / 3 / 2023 | |
|--|--|-------|---|---------|
| Site Name: <u>Starr 34 Fee #1H</u> API Number: <u>30-0 05 64018</u> Plug Date: <u>4 / 10 / 2020</u> | | | | |
| <input type="checkbox"/> Facility Site-No associated well on location | | | | |
| Inspection: <input type="checkbox"/> Initial <input type="checkbox"/> Monitoring <input type="checkbox"/> Active <input checked="" type="checkbox"/> Corrective <input type="checkbox"/> Final | | | YES | NO |
| Was this the last remaining or only well on the location? | | | ✓ | |
| Are there any abandoned pipelines that are going to remain on the location? | | | | ✓ |
| Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that are going to remain on location? | | | | ✓ |
| If any production equipment or structure (including 3rd party) is to remain on location, please specify. | | | | |
| Site Evaluation | | | | |
| Recontoured back to original State/Topsoil Replaced | | | YES | NO |
| Have the rat hole and cellar been filled and leveled? | | | ✓ | |
| Have the cathodic protection holes been properly abandoned & reclaimed? | | | ✓ | |
| Rock or Caliche Surfacing materials have been removed? | | | ✓ | |
| Section Comments: | | | | |
| All Facilities Removed for Final Reclamation | | | | |
| Have all of the pipelines & production equipment been cleared? (other than the listed above) | | | ✓ | |
| Has all of the required junk and trash been cleared from the location? | | | ✓ | |
| Have all of the required anchors, dead men, tie downs and rbers have been cut off at least two feet below ground level? | | | ✓ | |
| Have all of the required metal bolts and other materials have been removed? | | | ✓ | |
| Have all the required portable bases been removed? | | | ✓ | |
| Section Comments: | | | | |
| Dry Hole Marker | | | YES | NO |
| Has a steel marker been installed per COA requirements? | | | ✓ | |
| Check One: <input type="checkbox"/> Buried <input checked="" type="checkbox"/> Above Ground | | | | |
| Required DHM Information: | | | | |
| <input checked="" type="checkbox"/> Operator Name <input checked="" type="checkbox"/> U/L or Qtr <input checked="" type="checkbox"/> API Number <input checked="" type="checkbox"/> County <input type="checkbox"/> Federal Lease # (Fed Only) <input checked="" type="checkbox"/> Lease Name & Number <input checked="" type="checkbox"/> Sec-Tier-Ring <input checked="" type="checkbox"/> Footage <input checked="" type="checkbox"/> P&A Date | | | | |
| Free of Oil or Salt Contaminated Soil | | | YES | NO |
| Have all the required pits been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan? | | | ✓ | |
| Have all other environmental concerns been addressed as per OCD rules? | | | ✓ | |
| If any environmental concerns remain on the location, please specify. | | | | |
| Abandoned Pipelines | | | | |
| Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19. 15. 35. 10 NM4C). | | | YES | NO |
| Have all fluids have been removed from any abandoned pipelines? | | | | |
| Have all abandoned pipelines been confirmed to NOT contain additional regulated NORM, other than that which accumulated under normal operation? | | | | |
| Have all accessible points of abandoned pipelines been permanently capped? | | | | |
| Section Comments: | | | | |
| Last Remaining or Only Well on the Location | | | YES | NO |
| Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location. | | | | |
| Have all electrical service poles and lines been removed from the location? | | | ✓ | |
| Is there any electrical utility distribution infrastructure that is remaining on the location? | | | | ✓ |
| Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan? | | | ✓ | |
| Have all the retrievable pipelines, production equipment been removed from the location? | | | ✓ | |
| Has all the junk and trash been removed from the location? | | | ✓ | |
| Section Comments: | | | | |
| Environmental Only: Do not have to be met to pass inspection | | | Met | Not Met |
| This section corresponds with questions on the Reclamation Inspection Form in Environmental but not related to NMOC forms. | | | | |
| Free of Noxious or Invasive Weeds? (Note species or treatment in remarks) | | | ✓ | |
| Site Stability? Erosion controls in place (if necessary) & working. | | | | ✓ |
| Signs of seedling completion? (Broadcast/Drilled) | | | | ✓ |
| Revegetation Success as compared to background? Met >75%. Circle One: <u>(0%)</u> 25% 50% 75% 100% | | | | ✓ |
| Adequate Reclamation Fence installed? | | | | ✓ |
| Section Comments: | | | | |
| Additional Findings or Comments: <u>Piles of fertilizer on south & north sides of pad.</u> | | | | |
| Inspector: <u>Igor Rios</u> | | | | |
| <input type="checkbox"/> READY FOR SAN SUBMITTAL <input type="checkbox"/> NEEDS FURTHER REVIEW | | | | |
| Picture Checklist: <input checked="" type="checkbox"/> DHM <input checked="" type="checkbox"/> Background <input type="checkbox"/> 3rd Party Equipment <input type="checkbox"/> Contamination <input type="checkbox"/> <input checked="" type="checkbox"/> Site Corners <input type="checkbox"/> Access Road <input type="checkbox"/> BOG Equipment <input type="checkbox"/> Trash/Junk <input type="checkbox"/> | | | Inspection Result <input checked="" type="radio"/> PASS <input type="radio"/> FAIL | |

On-Site_Inspection_Form v1.xlsx

2/13/2023

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

DEFINITIONS

Action 196700

DEFINITIONS

| | |
|--|---|
| Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702 | OGRID: 7377 |
| | Action Number: 196700 |
| | Action Type: [C-103] Sub. Release After P&A (C-103Q) |

DEFINITIONS

| |
|--|
| For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application: <ul style="list-style-type: none">• lease and well location, hereinafter "location";• flowlines or pipelines, hereinafter "pipelines";• and non-retrieved or abandoned, hereinafter "abandoned". |
|--|

District I

1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 196700

QUESTIONS

| | |
|--|---|
| Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702 | OGRID: 7377 |
| | Action Number: 196700 |
| | Action Type: [C-103] Sub. Release After P&A (C-103Q) |

QUESTIONS

| Subsequent Report of: Location Ready For OCD Inspection After P&A | |
|---|---|
| Was this the last remaining or only well on the location | Yes |
| Are there any abandoned pipelines that are going to remain on the location | No |
| Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that is going to remain on the location | No |
| If any production equipment or structure is to remain on the location, please specify | Will not seed per Landowner. Letter attached. |

Site Evaluation

Please answer all the questions in this group.

| | |
|---|--|
| Have all the required pits been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan | Yes |
| Have the rat hole and cellar been filled and leveled | Yes |
| Have the cathodic protection holes been properly abandoned | Yes |
| Has a steel marker, at least 4 inches in diameter and at least 4 feet above ground level, been set in concrete | Yes |
| The (concrete-set) steel marker shows: Must attach marker photograph(s). * | THE OPERATOR NAME, LEASE NAME AND WELL NUMBER AND LOCATION, INCLUDING UNIT LETTER, SECTION, TOWNSHIP AND RANGE, SHALL BE WELDED, STAMPED OR OTHERWISE PERMANENTLY ENGRAVED INTO THE MARKER'S METAL. |
| Has the location been leveled as nearly as possible to original ground contour | Yes |
| Have all the required pipelines and other production equipment been cleared | Yes |
| Has all the required junk and trash been cleared from the location | Yes |
| Have all the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level | Yes |
| Have all the required metal bolts and other materials have been removed | Yes |

Poured onsite concrete bases do not have to be removed.

| | |
|--|---------------|
| Have all the the required portable bases been removed | Yes |
| Have all other environmental concerns have been addressed as per OCD rules | Yes |
| If any environmental concerns remain on the location, please specify | Not answered. |

* Proof of the site marker (photograph) is required.

Please submit any other site photographs that would assist in documenting the above answers, site features, additional concerns, or other nearby / remaing structures and equipment.

District I

1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 2

Action 196700

QUESTIONS (continued)

| | |
|--|---|
| Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702 | OGRID: 7377 |
| | Action Number: 196700 |
| | Action Type: [C-103] Sub. Release After P&A (C-103Q) |

QUESTIONS

| Abandoned Pipelines | |
|---|----------------------|
| <i>Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19.15.35.10 NMAC).</i> | |
| Have all fluids have been removed from any abandoned pipelines | <i>Not answered.</i> |
| Have all abandoned pipelines been confirmed to NOT contain additional regulated NORM, other than that which accumulated under normal operation | <i>Not answered.</i> |
| Have all accessible points of abandoned pipelines been permanently capped | <i>Not answered.</i> |

| Last Remaining or Only Well on the Location | |
|--|-----|
| <i>Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.</i> | |
| Have all electrical service poles and lines been removed from the location | Yes |
| Is there any electrical utility distribution infrastructure that is remaining on the location | No |
| Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan | Yes |
| Have all the retrievable pipelines, production equipment been removed from the location | Yes |
| Has all the junk and trash been removed from the location | Yes |

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 196700

ACKNOWLEDGMENTS

| | |
|--|---|
| Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702 | OGRID: 7377 |
| | Action Number: 196700 |
| | Action Type: [C-103] Sub. Release After P&A (C-103Q) |

ACKNOWLEDGMENTS

| | |
|-------------------------------------|--|
| <input checked="" type="checkbox"/> | I hereby certify that all the work has been completed for this location and the site is ready for an OCD scheduled inspection. |
|-------------------------------------|--|

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 196700

CONDITIONS

| | |
|--|---|
| Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702 | OGRID: 7377 |
| | Action Number: 196700 |
| | Action Type: [C-103] Sub. Release After P&A (C-103Q) |

CONDITIONS

| | | |
|------------|-----------|----------------|
| Created By | Condition | Condition Date |
| gcordero | None | 3/28/2023 |