

Well Name: OMLER A	Well Location: T28N / R10W / SEC 35 / NWNW / 36.62347 / -107.87032	County or Parish/State: SAN JUAN / NM
Well Number: 2E	Type of Well: CONVENTIONAL GAS WELL	Allottee or Tribe Name:
Lease Number: NMSF077085	Unit or CA Name:	Unit or CA Number:
US Well Number: 3004524116	Well Status: Producing Gas Well	Operator: HILCORP ENERGY COMPANY

Subsequent Report

Sundry ID: 2735473

Type of Submission: Subsequent Report	Type of Action: Workover Operations
Date Sundry Submitted: 06/14/2023	Time Sundry Submitted: 06:39
Date Operation Actually Began: 06/07/2023	

Actual Procedure: Please see attached summary of workover operations.

SR Attachments

Actual Procedure

OMLER_A_2E_Subseq_Pkr_Repair_20230614063819.pdf

Received by OCD: 6/14/2023 11:25:20 AM

Page 2 of 7

Well Name: OMLER A	Well Location: T28N / R10W / SEC 35 / NWNW / 36.62347 / -107.87032	County or Parish/State: SAN JUAN / NM
Well Number: 2E	Type of Well: CONVENTIONAL GAS WELL	Allottee or Tribe Name:
Lease Number: NMSF077085	Unit or CA Name:	Unit or CA Number:
US Well Number: 3004524116	Well Status: Producing Gas Well	Operator: HILCORP ENERGY COMPANY

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: TAMMY JONES	Signed on: JUN 14, 2023 06:38 AM
Name: HILCORP ENERGY COMPANY	
Title: Regulatory Compliance Specialist	
Street Address: 382 ROAD 3100	
City: AZTEC	State: NM
Phone: (505) 324-5185	
Email address: tajones@hilcorp.com	

Field

Representative Name:		
Street Address:		
City:	State:	Zip:
Phone:		
Email address:		

BLM Point of Contact

BLM POC Name: KENNETH G RENNICK	BLM POC Title: Petroleum Engineer
BLM POC Phone: 5055647742	BLM POC Email Address: krennick@blm.gov
Disposition: Accepted	Disposition Date: 06/14/2023
Signature: Kenneth Rennick	

OMLER A 2E

30.045.24116

PACKER REPAIR

6/7/2023 – MIRU. BD WELL. ND WH. NU BOP, FUNCTION & PT BOP (GOOD). PULL TBG HANGER. TOO H W/2-3/8" TBG. INSPECT SEAL ASSEMBLY, BOTTOM SEALS LOOK BAD, TOP SEALS LOOK NEW. TIH W/PKR PLUCKER, JARS & DRILL COLLARS TO TOL @ 3054'. SWI. SDFN.

6/8/2023 – EST CIRC W/AIR/FOAM UNIT. UNLOAD HOLE. P/U SWIVEL. EST CIRC W/AIR/FOAM UNIT. TAG PACKER @ 6261'. WASHOVER 4-1/2" PKR to 6265'. CIRC HOLE CLEAN. TOO H W/SWIVEL, NO FISH. TIH W/JUNK MILL TO 3130'. TOO H TO ABOVE TOL. SWI. SDFN.

6/9/2023 – EST CIRC & UNLOAD HOLE. TAG TOP OF FISH @ 6386'. ATTEMPT TO WASH OVER. MILL ON FISH @ 6386' to 6473'. CIRC PKR PARTS BACK TO SURFACE. TOO H W/FISHING TOOLS & PKR FISH. DRIFT PROD TBG TO 2573'. SWI. SDFN.

6/12/2023 – M/U PKR SEAL ASSMBLY & TIH ON 2-3/8" PROD TBG. SPACE OUT SEAL ASSMBLY & M/U TBG HANGER & LAND TBG W/199 JTS 2-3/8" 4.7# J-55 TBG SET @ 6367'. SN @ 6366'. PKR @ 6244'. ND BOP. NU WH. PT TBG W/AIR TO 500 PSI, GOOD. RD. RIG RELEASED.

6/12/2023 – TO CONFIRM ZONAL ISOLATION, A WITNESSED PACKER TEST WITHIN 30 DAYS AFTER RIG WORK WILL BE SCHEDULED WITH AGENCIES, PER MONICA KUEHLING, NMOCD (see attached email).

Tammy Jones

From: Kuehling, Monica, EMNRD <monica.kuehling@emnrd.nm.gov>
Sent: Monday, June 12, 2023 12:06 PM
To: Laura Bohorquez; Tammy Jones; Daniel Hurd; Kelly Davidson
Cc: Farmington Regulatory Techs; Issac Overright - (C); Jose Morales
Subject: RE: [EXTERNAL] Re: OMLER A 2E - 90 Days to Fix or Plug due 6/13/2023

CAUTION: External sender. DO NOT open links or attachments from UNKNOWN senders.

Please perform packer test within 30 days after rig move with prior approval from the BLM

Include all email chains in subsequent

Thank you

Monica Kuehling
Compliance Officer Supervisor
Deputy Oil and Gas Inspector
New Mexico Oil Conservation Division
North District
Office Phone: 505-334-6178 ext. 123
Cell Phone: 505-320-0243
Email - monica.kuehling@emnrd.nm.gov

From: Laura Bohorquez <Laura.Bohorquez@hilcorp.com>
Sent: Monday, June 12, 2023 11:32 AM
To: Tammy Jones <tajones@hilcorp.com>; Daniel Hurd <dhurd@hilcorp.com>; Kelly Davidson <mdavidson@hilcorp.com>; Kuehling, Monica, EMNRD <monica.kuehling@emnrd.nm.gov>
Cc: Farmington Regulatory Techs <FarmingtonRegulatoryTechs@hilcorp.com>; Issac Overright - (C) <Issac.Overright@hilcorp.com>; Jose Morales <jomorales@hilcorp.com>
Subject: [EXTERNAL] Re: OMLER A 2E - 90 Days to Fix or Plug due 6/13/2023

CAUTION: This email originated outside of our organization. Exercise caution prior to clicking on links or opening attachments.

All,

We have replaced the packer on this dual completion well, we will be rigging down today 6/12. Just confirmed with Monica on the phone, and we will perform a Packer test 30 days after rig work to confirm zonal isolation.

Thanks
Laura

Get [Outlook for iOS](#)

From: Tammy Jones <tajones@hilcorp.com>

Sent: Wednesday, March 15, 2023 9:29:15 AM

To: Laura Bohorquez <Laura.Bohorquez@hilcorp.com>; Daniel Hurd <dhurd@hilcorp.com>; Kelly Davidson <mdavidson@hilcorp.com>

Cc: Farmington Regulatory Techs <FarmingtonRegulatoryTechs@hilcorp.com>

Subject: OMLER A 2E - 90 Days to Fix or Plug due 6/13/2023

Hi Laura,

Please see attached NMOCD Conditions of Approval.

Thanks,

Tammy Jones | **HILCORP ENERGY COMPANY** | San Juan Regulatory | 505.324.5185 | tajones@hilcorp.com

From: OCDOnline@state.nm.us <OCDOnline@state.nm.us>

Sent: Wednesday, March 15, 2023 9:21 AM

To: Tammy Jones <tajones@hilcorp.com>

Subject: [EXTERNAL] The Oil Conservation Division (OCD) has approved the application, Application ID: 197245

CAUTION: External sender. DO NOT open links or attachments from UNKNOWN senders.

To whom it may concern (c/o Tammy Jones for HILCORP ENERGY COMPANY),

The OCD has approved the submitted Subsequent Report - Remedial Workover (C-103R), for API number (30-#) 30-045-24116, with the following conditions:

- for record only - repair and then packer test dated 3/15/2023 - this is a failed packer test - 90 days to fix or plug
- this is second packer failure - Submit NOI for repair as soon as possible

The signed C-103R can be found in the OCD Online: Imaging under the API number (30-#).

If you have any questions regarding this application, please contact me.

Thank you,

Monica Kuehling

OCD Inspector

505-334-6178

monica.kuehling@emnrd.nm.gov

New Mexico Energy, Minerals and Natural Resources Department

1220 South St. Francis Drive

Santa Fe, NM 87505

The information contained in this email message is confidential and may be legally privileged and is intended only for the use of the individual or entity named above. If you are not an intended recipient or if you have received this message in error, you are hereby notified that any dissemination, distribution, or copy of this email is strictly prohibited. If you have received this email in error, please immediately notify us by return email or telephone if the sender's phone number is listed above, then promptly and permanently delete this message.

While all reasonable care has been taken to avoid the transmission of viruses, it is the responsibility of the recipient to ensure that the onward transmission, opening, or use of this message and any attachments will not adversely affect its systems or data. No responsibility is accepted by the company in this regard and the recipient should carry out such virus and other checks as it considers appropriate.




Current Schematic - Version 3

Well Name: OMLER A 02E

API / UWI 3004524116	Surface Legal Location 035-028N-010W-D	Field Name CH/DK DUAL	Route 0708	State/Province NEW MEXICO	Well Configuration Type
Ground Elevation (ft) 5,879.00	Original KB/RT Elevation (ft) 5,891.00	KB-Ground Distance (ft) 12.00	KB-Casing Flange Distance (ft) 12.00	KB-Tubing Hanger Distance (ft) 12.00	

Original Hole



District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 227745

CONDITIONS

Operator: HILCORP ENERGY COMPANY 1111 Travis Street Houston, TX 77002	OGRID: 372171
	Action Number: 227745
	Action Type: [C-103] Sub. Workover (C-103R)

CONDITIONS

Created By	Condition	Condition Date
mkuehling	Notify this office 24 hours prior to performing packer test - if bradenhead test was not performed while rig was on - one will need to be performed and witnessed by this office	6/23/2023