Form 3160-5 (June 2019)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPR	OVED
OMB No. 100-	4-0137
Expires: October	31, 20

BUREAU OF LAND MANAGEMENT	
LINDRY NOTICES AND REPORTS ON WELLS	

BUREAU OF LAND MAN	AGEMENT		5. Lease Serial No. NMSF078767		
SUNDRY NOTICES AND REPO Do not use this form for proposals t abandoned well. Use Form 3160-3 (A	o drill or to re-	enter an	6. If Indian, Allottee of		
SUBMIT IN TRIPLICATE - Other instru	uctions on page 2		7. If Unit of CA/Agre	ement, Name and/or No.	
1. Type of Well			NMNM78407E		
Oil Well X Gas Well Other			8. Well Name and No).	
2. Name of Operator			Rosa Unit 19D 9. API Well No.		
LOGOS Operating, LLC			9. API Well No. 30-039-30781		
3a. Address	3b. Phone No. (inclu	de area code)	10. Field and Pool or	Exploratory Area	
2010 Afton Place, Farmington NM 87401	505-278-8720			e / Basin Dakota / Basin Mancos	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)			11. Country or Parish		
Unit L, Section 24 T31N R06W 1980' FSL & 660' FWL				, Suite	
<u> </u>			Rio Arriba, NM		
12. CHECK THE APPROPRIATE BO	OX(ES) TO INDICAT	TE NATURE OF NOT	ICE, REPORT OR OTI	HER DATA	
TYPE OF SUBMISSION		TYPE OF AC	TION		
Acidize	Deepen	Proc	duction (Start/Resume)	Water Shut-Off	
x Notice of Intent Actulze Alter Casing	Hydraulic 1	=	lamation	Well Integrity	
— Casina Dansin	New Const	· =	omplete	X Other Wellbore Isolation/	
Subsequent Report Casing Repair Change Plans	Plug and A		porarily Abandon	Pressure Monitoring	
Final Abandonment Notice Convert to Injection	Plug Back	=	er Disposal		
Attach the Bond under which the work will be performed or profollowing completion of the involved operations. If the operation testing has been completed. Final Abandonment Notices must be determined that the site is ready for final inspection.) LOGOS Operating request to conduct a wellbore isolat Pad 29 completions. In order to preserve wellbore integwellbore and actively monitor pressure via downhole g	n results in a multiple e filed only after all re ion for subject well grity and protect the	completion or recompequirements, including 1. The Rosa Unit 191 2. remaining reserves	pletion in a new interval reclamation, have been D is at risk of catastro s of the well, it is reco	l, a Form 3160-4 must be filed once a completed and the operator has ophic failure from the nearby ommended to isolate the	
4. I hereby certify that the foregoing is true and correct. Name (Pri					
Etta Trujillo	Title	Regulatory Spe	cialist		
Signature Eta Trujillo	Date	8/2/2023			
THE SPACE	FOR FEDERA	L OR STATE O	FICE USE		
Approved by					
·					
		Title		Date	
Conditions of approval, if any, are attached. Approval of this notice certify that the applicant holds legal or equitable title to those rights which would entitle the applicant to conduct operations thereon		Office			

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

11 6 6 1 1	
U.S. Department	of the interior
	-,
BUREAU OF LAND	MANNACEMENT
DUKEAU OF LAND	MANAGEMENT

Well Name	Well Number	US Well Number	Lease Number	Case Number	Operator
ROSA UNIT	19D	300393078100C3	NMSF078767	NMNM78407A	LOGOS
ROSA UNIT	19D	300393078100C2	NMSF078767	NMNM78407E	LOGOS
ROSA UNIT	19D	300393078100C1	NMSF078767	NMNM78407A	LOGOS

Notice of Intent

Sundry ID: 2744222

Type of Submission: Notice of Intent Type of Action: Other

Date Sundry Submitted: 08/02/2023 Time Sundry Submitted: 02:13

Date proposed operation will begin: 08/02/2023

Procedure Description: LOGOS Operating request to conduct a wellbore isolation for subject well. The Rosa Unit 19D is at risk of catastrophic failure from the nearby Pad 29 completions. In order to preserve wellbore integrity and protect the remaining reserves of the well, it is recommended to isolate the wellbore and actively monitor pressure via downhole gauge for a total well observation period of 9-12 months. See attached procedure.

Surface Disturbance

Is any additional surface disturbance proposed?: No

NOI Attachments

Procedure Description

3160_5_Rosa_Unit_19D_NOI_Wellbore_Isolation_Pressure_Monitoring_20230802_20230802140339.pdf

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: ETTA TRUJILLO **Signed on**: AUG 02, 2023 02:12 PM

Name: LOGOS OPERATING LLC

Title: Regulatory Specialist

Street Address: 2010 AFTON PLACE

City: Farmington State: NM

Phone: (505) 324-4154

Email address: ETRUJILLO@LOGOSRESOURCESLLC.COM

Field

Representative Name:

Street Address:

City: State: Zip:

Phone:

Email address:

BLM Point of Contact

BLM POC Name: KENNETH G RENNICK

BLM POC Title: Petroleum Engineer

BLM POC Phone: 5055647742 BLM POC Email Address: krennick@blm.gov

Disposition: Approved **Disposition Date:** 08/03/2023

Signature: Kenneth Rennick



WELLBORE ISOLATION/PRESSURE MONITORING-NMOCD (2023)

Rosa Unit 019D
30-039-30781
1980' FSL & 660' FWL
Section 24, T31N, R06W
Rio Arriba, New Mexico
LAT: 36.8833084° N LONG: -107.4208908° W
Mesaverde/Mancos/Dakota

PROJECT OBJECTIVE:

The Rosa Unit 19D is at risk of catastrophic failure from the nearby Pad 29 completions. In order to preserve wellbore integrity and protect the remaining reserves of the well, it is recommended to isolate the wellbore and actively monitor pressure via downhole gauge for a total observation period of 9-12 months.

WORKOVER PROCEDURE:

- 1. Hold safety meeting. MIRU workover rig. Place fire and safety equipment in strategic locations. Comply with all LOGOS, BLM, and NMOCD rules and regulations.
- 2. Lay flow lines. Check and record casing and tubing pressures. Sell pressure down to line. Kill well if necessary.
- 3. Nipple down wellhead and nipple up BOP.
- 4. TOOH and stand back tubing.
- 5. Set bridge plug within 50' of the Dakota perforations.
- 6. TIH and set cement retainer at ~6910'.
- 7. RIH with pressure gauge and tubing and sting into retainer.
- 8. Leave well shut in during offset completions and post completions for pressure monitoring.
- 9. Once offset completions are complete and adequate pressure monitoring data has been collected, TOOH with tubing and laydown pressure gauge.
- 10. Trip in hole and mill out cement retainer and bridge plug.
- 11. Run 2-3/8" tubing back in hole and return well to production.

Depths (KB):



Wellbore Schematic

Well Name: Rosa Unit 019D Unit L Sec 24, T31N, R06W 1980' FSL & 660' FWL Location: County: Rio Arriba, NM API#: 30-039-30781 Co-ordinates: Lat 36.8833084 Long -107.4208908 NAD83 Elevations: GROUND: 6311' KB: 6325

PBTD:


TD:

8157

8164

Last Updated: 7/13/2023 Moss Reviewed by: Spud Date: 8/25/2009 Completion Date 11/16/2009 Last Workover Date: 5/27/2011 Last Updated:

8075 ft



Surface Casing: (8/25/2009)

Drilled a 14-3/4" surface hole to 320'. Set 7 jts 10-3/4", 40.5#, J-55 csg at 313' Cmt w/ 300 sx Type 3 cmt (539 ft3, 13.5 ppg, 1.796 yield), circ 60 bbls to surface

TOC at surface (circ) Intermediate Casing: (9/4/2009)

Drilled a 9-7/8" intermediate hole to 3872'. Set 88 jts 7-5/8", 26.4#, K-55 csg at 3862' Cmt w/ 490 sx Extendcem cmt (1338 ft3, 11.5 ppg, 2.73 yield). Tail w/ 100sx Premium cmt (118 ft3, 15.6 ppg, 1.18 yield). Circ 100 bbls cmt to surface.

Production Casing: (9/9/2007)

Drilled a 6-3/4" production hole to 8164'. Set 213 jts 5-1/2", 17#, N-80 csg at 8164' Cmt w/ 360 sx Fraccem cmt (504 ft3, 13.1 ppg, 1.4 yield). TOC at 3490' (CBL 9/16/2009)

Tubing: (05/2011) Length (ft) KB 14 (109) 2-3/8", 4.7#, N-80 tbg jts 3484 *est length (142) 2-3/8", 4.7#, J-55 tbg jts 4543 *est length (1) 1.78" F nipple at 8042 (1) 2-3/8", 4.7#, J-55 tbg jt 32 (1) 1/2 Muleshoe 1

Set at: Artificial Lift:

Plunger lift

Perforations: (11/2009)

DK: (8031'-8149'): 78, 034" holes. 8031', 35, 39, 43, 47, 51, 55, 59, 63, 69, 77, 81, 85 89, 93, 97, 8101', 05, 13, 17, 21, 25, 29, 33, 47, 8149'. Acidize w/ 1993 gal 15% HCL acid. Frac w/ 4,971# 100 mesh sand & 64,277# 40/70 sand in 2519 bbls frac fluid.

L MC (7272'-7734'): 81, 0.34" holes. 7272', 82, 92, 99, 7308', 18, 28, 38, 48, 56, 65, 74 86, 97, 7407', 14, 24, 34, 44, 7531', 43, 63, 7703', 11, 17, 25, 7734'. Acidize w/ 2431 gal 15% FE acid. Frac w/ 6,396# 100 mesh sand & 98,292# 40/70 sand in 10,098 gal frac fluid

U MC (6960'-7220'): 81, 0.34" holes. 6960', 70, 80, 90, 7000', 10, 20, 30, 40, 50, 60, 70 80, 90, 7100', 10, 20, 30, 40, 50, 60, 70, 80, 90, 7200', 10, 7220'. Acidize w/ 1982 gal 15% FE

acid. Frac w/ 6406# 100 mesh sand & 92,349# 40/70 sand in 10,160 gal frac fluid. L MV (5816'-6181'): 69, 0.34" holes. 5816', 20, 24, 28, 32, 36, 40, 44, 48, 52, 56, 60, 64, 68, 72, 76, 80, 84, 88, 92, 96, 5900', 04, 08, 12, 16, 20, 24, 28, 32, 36, 40, 50, 54, 60, 64, 68,

80, 82, 96, 98, 6000', 12, 14, 16, 21, 40, 42, 44, 46, 58, 60, 68, 70, 72, 79, 88, 90, 92, 6103' 16, 18, 20, 36, 39, 47, 64, 68, 6181'. Acidize w/ 2000 gal 15% HCL.

Frac w/ 80,000# 20/40 sand in 13,000 gal frac fluid

U MV (5353'-5734'): 63, 0.34" holes. 5353', 59, 61, 69, 87, 93, 5405', 07, 19, 27, 39, 55, 62, 78, 92, 94, 96, 98, 5522', 24, 42, 44, 66, 68, 70, 76, 78, 80, 82, 84, 86, 88, 90, 92, 94, 96, 98, 5600', 02, 04, 06, 08, 28, 30, 32, 34, 36, 38, 40, 42, 44, 46, 48, 5714', 16, 18, 20, 22, 26, 28, 30, 32,

5734'. Acidized w/ 2000 gal 15% HCL. Frac w/ 81,120# 20/40 sand in 13,000 gal frac fluid.

FOITHAUGHS.
Lewis
Cliff Llaures

Lewis	3682'	Mancos	6270'
Cliff House	5562'	Dakota	8031'
Point Lookout	5814'		

Additional Notes:

(11/2009) Initial Completion. Perf'd & stim'd MV, MC, & DK formations. Trimingled upon completion (05/2010) Tagged fill at 8117' w/ slickline. CO to PBTD at 8157'. Ran spinner survey. EOT at 8100' (05/2011) Tag fill at 8096'. Pull tbg, no visible scale. CO to PBTD at 8157'. Ran another spinner survey. Set EOT at 8075


Max deviation 28.81° at 1563'. Max DLS 6.44 at 3698'.

PBTD - 8157' TD - 8164'



Proposed Wellbore Schematic

Well Name: Rosa Unit 019D Last Updated: 7/13/2023 Moss Unit L Sec 24, T31N, R06W 1980' FSL & 660' FWL Location: Reviewed by: County: Rio Arriba, NM Spud Date: 8/25/2009 API#: 30-039-30781 Completion Date 11/16/2009 Co-ordinates: Lat 36.8833084 Long -107.4208908 NAD83 Last Workover Date: 5/27/2011 GROUND: Flevations: 6311' Last Updated: KB: 6325 Depths (KB): PBTD: 8157



TD - 8164'

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 248724

CONDITIONS

Operator:	OGRID:	
LOGOS OPERATING, LLC	289408	
2010 Afton Place	Action Number:	
Farmington, NM 87401 248724		
	Action Type:	
	[C-103] NOI General Sundry (C-103X)	

CONDITIONS

Created By		Condition Date
dmcclure	None	8/11/2023