

Well Name: BOIS D` ARC DIVIDE 22	Well Location: T21N / R5W / SEC 22 / SENW / 36.036691 / -107.352168	County or Parish/State: SANDOVAL / NM
Well Number: 4	Type of Well: OIL WELL	Allottee or Tribe Name:
Lease Number: NMNM105533	Unit or CA Name:	Unit or CA Number:
US Well Number: 3004320980	Well Status: Abandoned	Operator: EOG RESOURCES INCORPORATED

Subsequent Report

Sundry ID: 2748246

Type of Submission: Subsequent Report	Type of Action: Reclamation
Date Sundry Submitted: 08/28/2023	Time Sundry Submitted: 12:06
Date Operation Actually Began: 06/29/2023	

Actual Procedure: P&A Reclamation and seeding (6/29/23) was completed on 8/14/23 and an onsite was conducted on 8/14/23 with BLM-RPFO. EOG will conduct annual monitoring beginning in 2024 and will submit a sundry advising of the status of reclamation success. Upon meeting BLM’s success criteria, a Final Abandonment Notice will be submitted.

SR Attachments

Actual Procedure

BOIS_D_ARC_DIVIDE_22_004__CRR_2023_8_28_20230828120544.pdf

Well Name: BOIS D ARC DIVIDE 22	Well Location: T21N / R5W / SEC 22 / SENW / 36.036691 / -107.352168	County or Parish/State: SANDOVAL / NM
Well Number: 4	Type of Well: OIL WELL	Allottee or Tribe Name:
Lease Number: NMNM105533	Unit or CA Name:	Unit or CA Number:
US Well Number: 3004320980	Well Status: Abandoned	Operator: EOG RESOURCES INCORPORATED

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: LACEY GRANILLO

Signed on: AUG 28, 2023 12:05 PM

Name: EOG RESOURCES INCORPORATED

Title: Contractor Regulatory Specialist

Street Address: 104 SOUTH FOURTH STREET

City: ARTESIAState: NM

Phone: (575) 909-5284

Email address: LACEY_GRANILLO@EOGRESOURCES.COM

Field

Representative Name:

Street Address:

City:State:Zip:

Phone:

Email address:

BLM Point of Contact

BLM POC Name: DAVE J MANKIEWICZ

BLM POC Title: AFM-Minerals

BLM POC Phone: 5055647761

BLM POC Email Address: DMANKIEW@BLM.GOV

Disposition: Accepted

Disposition Date: 09/06/2023

Signature: Dave J Mankiewicz



Surface Reclamation Complete Report

Well Name: BOIS D ARC DIVIDE 22 #004

API: 30-043-20980

Well Location: F-22-21N-5W

Surface Owner: BLM

Reclamation Complete Date: 8/14/23



Date & Time: Sat Aug 14 14:04:32 MDT 2023
Footprint: 405685647 / 107351717
Altitude: 5770ft
Elevation: 5800-59
Approximate Bearing: 127° / 120° / 120° (all 0.1m)
Zone: 10
C. Peterson



On-Site Regulatory Reclamation Inspection		Date:	8/14/23
Site Name:	Bois D Arc Divide 22 #004		
API Number:	30-0-43-20980	Plat Date:	3/9/23
Inspection:		<input type="checkbox"/> Initial	<input type="checkbox"/> Monitoring
		<input type="checkbox"/> Active	<input type="checkbox"/> Corrective
<input type="checkbox"/> Facility Site- No associated well on location		<input checked="" type="checkbox"/> Final	
Was this the last remaining or only well on the location?		YES	NO
<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Are there any abandoned pipelines that are going to remain on the location?			<input checked="" type="checkbox"/>
Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that are going to remain on location?			<input checked="" type="checkbox"/>
If any production equipment or structure (including 3rd party) is to remain on location, please specify.			
Site Evaluation			
Recontoured back to original State/Topsil Replaced		YES	NO
Have the rat hole and cellar been filled and leveled?		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Have the cathodic protection holes been properly abandoned & reclaimed?		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Rock or Caliche Surfacing materials have been removed?		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Section Comments:			
All Facilities Removed for Final Reclamation			
Have all of the pipelines & production equipment been cleared? (other than the listed above)		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Has all of the required junk and trash been cleared from the location?		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Have all of the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level?		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Have all of the required metal bolts and other materials have been removed?		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Have all the required portable bases been removed?		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Section Comments:			
Dry Hole Marker		YES	NO
Has a steel marker been installed per COA requirements?		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Check One: <input type="checkbox"/> Buried <input checked="" type="checkbox"/> Above Ground			
Required DHM Information:			
<input checked="" type="checkbox"/> Operator Name <input type="checkbox"/> UL or OVI/OI <input checked="" type="checkbox"/> API Number <input checked="" type="checkbox"/> County <input type="checkbox"/> Federal Lease # (Fed Only)			
<input type="checkbox"/> Lease Name & Number <input checked="" type="checkbox"/> Sec-Ten-Rng <input checked="" type="checkbox"/> Footage <input checked="" type="checkbox"/> FSA Date			
Free of Oil or Salt Contaminated Soil		YES	NO
Have all the required pits been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Have all other environmental concerns been addressed as per OCD rules?		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
If any environmental concerns remain on the location, please specify.			
Abandoned Pipelines			
Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19.35.35.30 NMOC).		YES	NO
Have all fluids have been removed from any abandoned pipelines?		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Have all abandoned pipelines been confirmed to NOT contain additional regulated NORM, other than that which accumulated under normal operation?		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Have all accessible points of abandoned pipelines been permanently capped?		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Section Comments:			
Last Remaining or Only Well on the Location		YES	NO
Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Have all electrical service poles and lines been removed from the location?		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Is there any electrical utility distribution infrastructure that is remaining on the location?		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Have all the retrievable pipelines, production equipment been removed from the location?		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Has all the junk and trash been removed from the location?		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Section Comments:			
Environmental Only: Do not have to be met to pass inspection		Met	Not Met
This section corresponds with questions on the Reclamation Inspection Form in Environmental but not related to NMOC forms.		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Free of Noxious or Invasive Weeds? (Note species or treatment in remarks)		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Site Stability? Erosion controls in place (if necessary) & working.		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Signs of seeding completion? (Broadcast/Drilled)		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Revegetation Success as compared to background? Met >75%.		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Adequate Reclamation Fence installed?		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Section Comments:			
Additional Findings or Comments:		PASSED FINAL INSPECTION WITH BUM-RPFO	
Inspector: C. PETERSON			
Picture Checklist:		<input type="checkbox"/> READY FOR FAN SUBMITTAL	
<input checked="" type="checkbox"/> Initial <input checked="" type="checkbox"/> Background <input type="checkbox"/> 3rd Party Equipment <input type="checkbox"/> Contamination <input type="checkbox"/>		<input type="checkbox"/> NEEDS FURTHER REVIEW	
<input checked="" type="checkbox"/> Site Closure <input checked="" type="checkbox"/> Access Road <input type="checkbox"/> EOG Equipment <input type="checkbox"/> Trash/Junk <input type="checkbox"/>		Inspection Result	
		<input checked="" type="radio"/> PASS <input type="radio"/> FAIL	

On-Site Inspection Form v1.xlsx

2/13/2023

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 262307

CONDITIONS

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 262307
	Action Type: [C-103] Sub. General Sundry (C-103Z)

CONDITIONS

Created By	Condition	Condition Date
dmcclosure	ACCEPTED FOR RECORD	9/11/2023