

Well Name: DEER CANYON	Well Location: T20S / R21E / SEC 35 / SWNW /	County or Parish/State: EDDY / NM
Well Number: 1	Type of Well: CONVENTIONAL GAS WELL	Allottee or Tribe Name:
Lease Number: NMNM25336	Unit or CA Name:	Unit or CA Number:
US Well Number: 300152528700X1	Well Status: Abandoned	Operator: EOG RESOURCES INCORPORATED

Subsequent Report

Sundry ID: 2685466

Type of Submission: Subsequent Report	Type of Action: Reclamation
Date Sundry Submitted: 08/03/2022	Time Sundry Submitted: 11:05
Date Operation Actually Began: 05/31/2022	

**Actual Procedure:** P&A Reclamation and re-seeding was completed on 5/31/2022. Please see attached Surface Reclamation Complete Report. EOG will conduct annual monitoring beginning in 2023 and will submit a sundry advising of the status of reclamation success. Upon meeting BLM's success criteria, a Final Abandonment Notice will be submitted.

SR Attachments

Actual Procedure

DEER\_CANYON\_SOUTH\_ACK\_FEDERAL\_COM\_1\_CRR\_2022\_7\_26\_20220803110523.pdf

Well Name: DEER CANYON	Well Location: T20S / R21E / SEC 35 / SWNW /	County or Parish/State: EDDY / NM
Well Number: 1	Type of Well: CONVENTIONAL GAS WELL	Allottee or Tribe Name:
Lease Number: NMNM25336	Unit or CA Name:	Unit or CA Number:
US Well Number: 300152528700X1	Well Status: Abandoned	Operator: EOG RESOURCES INCORPORATED

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: TINA HUERTA

Signed on: AUG 03, 2022 11:05 AM

Name: EOG RESOURCES INCORPORATED

Title: Regulatory Specialist

Street Address: 104 SOUTH FOURTH STREET

City: ArtesiaState: NM

Phone: (575) 748-4168

Email address: tina\_huerta@eogresources.com

Field

Representative Name:

Street Address:

City:State:Zip:

Phone:

Email address:

BLM Point of Contact

BLM POC Name: DEBORAH L MCKINNEY

BLM POC Title: Legal Instruments Examiner

BLM POC Phone: 5752345931

BLM POC Email Address: dmckinne@blm.gov

Disposition: Accepted

Disposition Date: 10/17/2022

Signature: Deborah McKinney



## Surface Reclamation Complete Report

**Well Name:** DEER CANYON SOUTH ACK FEDERAL COM #001

**API:** 30-015-25287

**Well Location:** E-35-20S-21E, EDDY COUNTY, NM

**Surface Owner:** BLM

**Reclamation Complete Date:** 5/31/22

**Total Acres reclaimed:** 2.10 acres

**Seed Mix:**

Mix	Species	lb/acre (Drilled)	lb/acre (Broadcast)
BLM #1 (For Loamy Soils)	Plains lovegrass	1.0	2.0
"	Sand dropseed	2.0	4.0
"	Sideoats grama	10.0	20.0
"	Plains Bristlegrass	4.0	8.0

Weights should be as pounds of pure live seed.

**Note:**

EOG will conduct an annual surface reclamation monitoring field visit in 2023 to determine if successful vegetation regrowth is established.





On-Site Regulatory Reclamation Inspection							Date: 7/26/22
Site Name: <u>Deer Canyon #1</u>							
API Number: 30-0 <u>1525257</u> Plug Date: <u>12/22/21</u> Program: <u>Initial</u> Annual							
Was this the last remaining or only well on the location?							YES NO
Are there any abandoned pipelines that are going to remain on the location?							YES NO
Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that are going to remain on location?							YES NO
If any production equipment or structure (including 3rd party) is to remain on location, please specify.							
<b>Site Evaluation</b>							
Recontoured back to original State/Topsoil Replaced							YES NO
Have the rat hole and cellar been filled and leveled?							YES NO
Have the cathodic protection holes been properly abandoned & reclaimed?							YES NO
Rock or Caliche Surfacing materials have been removed?							YES NO
Section Comments:							
<b>All Facilities Removed for Final Reclamation</b>							
Have all of the pipelines & production equipment been cleared? (other than the listed above)							YES NO
Has all of the required junk and trash been cleared from the location?							YES NO
Have all of the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level?							YES NO
Have all of the required metal bolts and other materials have been removed?							YES NO
Have all the required portable bases been removed?							YES NO
Section Comments:							
<b>Dry Hole Marker</b>							
Has a steel marker been installed per COA requirements?							YES NO
Check One: <input type="checkbox"/> Buried <input checked="" type="checkbox"/> Above Ground							
DHM Info	Operator Name	Lease Name & Number	UL-S-T-R	Qtr Section (Footage)	API #	Federal Lease # (Federal Only)	
Met							
Not Met							
<b>Free of Oil or Salt Contaminated Soil</b>							
Have all the required pits been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?							YES NO
Have all other environmental concerns been addressed as per OCD rules?							YES NO
If any environmental concerns remain on the location, please specify.							
<b>Abandoned Pipelines</b>							
Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19, 15, 35, 10 NMAC).							YES NO
Have all fluids have been removed from any abandoned pipelines?							YES NO
Have all abandoned pipelines been confirmed to <b>NOT</b> contain additional regulated NORM, other than that which accumulated under normal operation?							YES NO
Have all accessible points of abandoned pipelines been permanently capped?							YES NO
Section Comments:							
<b>Last Remaining or Only Well on the Location</b>							
Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.							YES NO
Have all electrical service poles and lines been removed from the location?							YES NO
Is there any electrical utility distribution infrastructure that is remaining on the location?							YES NO
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?							YES NO
Have all the retrievable pipelines, production equipment been removed from the location?							YES NO
Has all the junk and trash been removed from the location?							YES NO
Section Comments:							
<b>Environmental Only: Do not have to be met to pass inspection</b>							
This section corresponds with questions on the Reclamation Inspection Form in iEnvironmental but not related to NMOCD forms.							
Free of Noxious or Invasive Weeds? (Note species or treatment in remarks)							Met Not Met
Site Stability? Erosion controls in place (if necessary) & working.							Met Not Met
Signs of seeding completion? (Broadcast/Drilled)							Met Not Met
Revegetation Success as compared to background? Met >75%.							Met Not Met
Circle One: <u>0%</u> 25% 50% 75% 100%							
Adequate Reclamation Fence installed?							Met Not Met
Section Comments:							
Additional Findings or Comments:							
Inspector: <u>Isor Rios</u>							
Picture Checklist: <input checked="" type="checkbox"/> DHM <input checked="" type="checkbox"/> Background <input checked="" type="checkbox"/> 3rd Party Equipment <input type="checkbox"/> Contamination <input type="checkbox"/> <input type="checkbox"/> Site Corners <input type="checkbox"/> Access Road <input type="checkbox"/> EOG Equipment <input type="checkbox"/> Trash/Junk <input type="checkbox"/>							
<input type="checkbox"/> READY FOR FAN SUBMITTAL <input type="checkbox"/> NEEDS FURTHER REVIEW Inspection Result <input checked="" type="radio"/> <b>PASS</b> <input type="radio"/> <b>FAIL</b>							

On-Site\_Inspection\_Form v1.xlsx

7/7/2022

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 151603

CONDITIONS

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 151603
	Action Type: [C-103] Sub. General Sundry (C-103Z)

CONDITIONS

Created By	Condition	Condition Date
dmcclure	ACCEPTED FOR RECORD	9/29/2023