

**Well Name:** WHITETAIL ATW  
FEDERAL COM

**Well Location:** T20S / R21E / SEC 35 /  
NWSW /

**County or Parish/State:** EDDY /  
NM

**Well Number:** 1

**Type of Well:** CONVENTIONAL GAS  
WELL

**Allottee or Tribe Name:**

**Lease Number:** NMNM37826A

**Unit or CA Name:** DEER CANYON SO.  
ACK FED

**Unit or CA Number:**  
NMNM72551

**US Well Number:** 300153079600X1

**Well Status:** Abandoned

**Operator:** EOG RESOURCES  
INCORPORATED

### Subsequent Report

**Sundry ID:** 2687209

**Type of Submission:** Subsequent Report

**Type of Action:** Reclamation

**Date Sundry Submitted:** 08/15/2022

**Time Sundry Submitted:** 01:21

**Date Operation Actually Began:** 08/09/2022

**Actual Procedure:** P&A Reclamation and re-seeding was completed on 8/9/2022. Please see attached Surface Reclamation Complete Report. EOG will conduct annual monitoring beginning in 2023 and will submit a sundry advising of the status of reclamation success. Upon meeting BLM's success criteria, a Final Abandonment Notice will be submitted.

### SR Attachments

**Actual Procedure**

WHITETAIL\_ATW\_FEDERAL\_COM\_1\_CRR\_2022\_812\_20220815132119.pdf

Well Name: WHITETAIL ATW  
FEDERAL COM

Well Location: T20S / R21E / SEC 35 /  
NWSW /

County or Parish/State: EDDY /  
NM

Well Number: 1

Type of Well: CONVENTIONAL GAS  
WELL

Allottee or Tribe Name:

Lease Number: NMNM37826A

Unit or CA Name: DEER CANYON SO.  
ACK FED

Unit or CA Number:  
NMNM72551

US Well Number: 300153079600X1

Well Status: Abandoned

Operator: EOG RESOURCES  
INCORPORATED

### Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: TINA HUERTA

Signed on: AUG 15, 2022 01:21 PM

Name: EOG RESOURCES INCORPORATED

Title: Regulatory Specialist

Street Address: 104 SOUTH FOURTH STREET

City: Artesia

State: NM

Phone: (575) 748-4168

Email address: tina\_huerta@eogresources.com

### Field

Representative Name:

Street Address:

City:

State:

Zip:

Phone:

Email address:

### BLM Point of Contact

BLM POC Name: DEBORAH L MCKINNEY

BLM POC Title: Legal Instruments Examiner

BLM POC Phone: 5752345931

BLM POC Email Address: dmckinne@blm.gov

Disposition: Accepted

Disposition Date: 06/16/2023

Signature: Deborah McKinney



## Surface Reclamation Complete Report

**Well Name:** WHITETAIL ATW FEDERAL COM #001

**API:** 30-015-30796

**Well Location:** M-35-20S-21E

**Surface Owner:** BLM

**Reclamation Complete Date:** 8/9/22

**Total Acres reclaimed:** 1.75 acres

**Seed Mix:**

Mix	Species	lb/acre (Drilled)	lb/acre (Broadcast)
BLM #1 (For Loamy Soils)	Plains lovegrass	1.0	2.0
"	Sand dropseed	2.0	4.0
"	Sideoats grama	10.0	20.0
"	Plains Bristlegrass	4.0	8.0

Weights should be as pounds of pure live seed.

**Note:**

EOG will conduct an annual surface reclamation monitoring field visit in 2023 to determine if successful vegetation regrowth is established.





**On-Site Regulatory Reclamation Inspection** Date: 8.11.2022

Site Name: White Tail ATw Federal Com #001

API Number: 30-0 15-30796 Plug Date: 10/12/21 Program: Initial Annual

Was this the last remaining or only well on the location? YES  NO

Are there any abandoned pipelines that are going to remain on the location? YES  NO

Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that are going to remain on location? YES  NO

If any production equipment or structure (including 3rd party) is to remain on location, please specify.

**Site Evaluation**

**Recontoured back to original State/Topsoil Replaced**

Have the rat hole and cellar been filled and leveled? YES  NO

Have the cathodic protection holes been properly abandoned & reclaimed? YES  NO

Rock or Caliche Surfacing materials have been removed? YES  NO

Section Comments:

**All Facilities Removed for Final Reclamation**

Have all of the pipelines & production equipment been cleared? (other than the listed above) YES  NO

Has all of the required junk and trash been cleared from the location? YES  NO

Have all of the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level? YES  NO

Have all of the required metal bolts and other materials have been removed? YES  NO

Have all the required portable bases been removed? YES  NO

Section Comments:

**Dry Hole Marker**

Has a steel marker been installed per COA requirements? YES  NO

Check One:  Buried  Above Ground

DHM Info	Operator Name	Lease Name & Number	UL-S-T-R	Qtr Section (Footage)	API #	Federal Lease # (Federal Only)
Met	<input checked="" type="checkbox"/>					
Not Met						

**Free of Oil or Salt Contaminated Soil**

Have all the required pits been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan? YES  NO

Have all other environmental concerns been addressed as per OCD rules? YES  NO

If any environmental concerns remain on the location, please specify.

**Abandoned Pipelines**

Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19. 15. 35. 10 NMAC).

Have all fluids have been removed from any abandoned pipelines? YES  NO

Have all abandoned pipelines been confirmed to NOT contain additional regulated NORM, other than that which accumulated under normal operation? YES  NO

Have all accessible points of abandoned pipelines been permanently capped? YES  NO

Section Comments:

**Last Remaining or Only Well on the Location**

Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.

Have all electrical service poles and lines been removed from the location? YES  NO

Is there any electrical utility distribution infrastructure that is remaining on the location? YES  NO

Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan? YES  NO

Have all the retrievable pipelines, production equipment been removed from the location? YES  NO

Has all the junk and trash been removed from the location? YES  NO

Section Comments:

**Environmental Only - Do not have to be met to pass inspection**

This section corresponds with questions on the Reclamation Inspection Form in iEnvironmental but not related to NMOCD forms.

Free of Noxious or Invasive Weeds? (Note species or treatment in remarks) Met  Not Met

Site Stability? Erosion controls in place (if necessary) & working. Met  Not Met

Signs of seeding completion? (Broadcast/Drilled) Met  Not Met

Revegetation Success as compared to background? Met >75%. Circle One: 0% 25% 50% 75% 100%

Adequate Reclamation Fence installed? Met  Not Met

Section Comments:

Additional Findings or Comments:

Inspector: \_\_\_\_\_

Picture Checklist:  DHM  Background  3rd Party Equipment  Contamination   
 Site Corners  Access Road  EOG Equipment  Trash/Junk

READY FOR FAN SUBMITTAL  
 NEEDS FURTHER REVIEW

Inspection Result:  PASS  FAIL

On-Site\_Inspection\_Form v1.xlsx 7/7/2022

**District I**  
 1625 N. French Dr., Hobbs, NM 88240  
 Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**  
 811 S. First St., Artesia, NM 88210  
 Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**  
 1220 S. St Francis Dr., Santa Fe, NM 87505  
 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 230359

**CONDITIONS**

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 230359
	Action Type: [C-103] Sub. General Sundry (C-103Z)

**CONDITIONS**

Created By	Condition	Condition Date
dmcclore	ACCEPTED FOR RECORD	9/29/2023