

Well Name: DAZED BDZ FEDERAL COM	Well Location: T21S / R24E / SEC 3 / LOT 13 / SWNW /	County or Parish/State: EDDY / NM
Well Number: 2	Type of Well: CONVENTIONAL GAS WELL	Allottee or Tribe Name:
Lease Number: NMNM0230377B	Unit or CA Name: 2 DAZED BDZ FEDERAL COM	Unit or CA Number: NMNM112721
US Well Number: 300153342800X2	Well Status: Abandoned	Operator: EOG RESOURCES INCORPORATED

Subsequent Report

Sundry ID: 2710360

Type of Submission: Subsequent Report

Date Sundry Submitted: 01/10/2023

Date Operation Actually Began: 01/03/2023

Type of Action: Reclamation

Time Sundry Submitted: 02:58

Actual Procedure: P&A Reclamation and re-seeding was completed on 1/3/2023. Please see attached Surface Reclamation Complete Report. EOG will conduct annual monitoring beginning in 2023 and will submit a sundry advising of the status of reclamation success. Upon meeting BLM's success criteria, a Final Abandonment Notice will be submitted.

SR Attachments

- Actual Procedure
- 3rd_Party_Reclamation_2_23_22_Approved_20230110145728.pdf

DAZED_BDZ_FEDERAL_COM_2_CRR_2023_1_10_20230110145518.pdf

Well Name: DAZED BDZ FEDERAL COM	Well Location: T21S / R24E / SEC 3 / LOT 13 / SWNW /	County or Parish/State: EDDY / NM
Well Number: 2	Type of Well: CONVENTIONAL GAS WELL	Allottee or Tribe Name:
Lease Number: NMNM0230377B	Unit or CA Name: 2 DAZED BDZ FEDERAL COM	Unit or CA Number: NMNM112721
US Well Number: 300153342800X2	Well Status: Abandoned	Operator: EOG RESOURCES INCORPORATED

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: TINA HUERTA	Signed on: JAN 10, 2023 02:58 PM
Name: EOG RESOURCES INCORPORATED	
Title: Regulatory Specialist	
Street Address: 104 SOUTH FOURTH STREET	
City: Artesia	State: NM
Phone: (575) 748-4168	
Email address: tina_huerta@eogresources.com	

Field

Representative Name:		
Street Address:		
City:	State:	Zip:
Phone:		
Email address:		

BLM Point of Contact

BLM POC Name: DEBORAH L MCKINNEY	BLM POC Title: Legal Instruments Examiner
BLM POC Phone: 5752345931	BLM POC Email Address: dmckinne@blm.gov
Disposition: Accepted	Disposition Date: 06/16/2023
Signature: Deborah McKinney	



Surface Reclamation Complete Report

Well Name: DAZED BDZ FEDERAL COM #002

API: 30-015-33428

Well Location: 13-03-21S-24E

Surface Owner: BLM

Reclamation Complete Date: 1/3/23

Total Acres reclaimed: 3 acres

Seed Mix:

Mix	Species	lb/acre (Drilled)	lb/acre (Broadcast)
BLM #3 (For Shallow Sites)	Plains Bristlegrass (<i>Setaria macrostachya</i>)	2.0	4.0
"	Green Sprangletop (<i>Leptochloa dubia</i>)	4.0	8.0
"	Sideoats Grama (<i>Bouteloua curtipendula</i>)	10.0	20.0

Weights should be as pounds of pure live seed.

Note:

EOG will conduct an annual surface reclamation monitoring field visit in 2023 to determine if successful vegetation regrowth is established.

3rd party risers on N side of location by the road.





On-Site Regulatory Reclamation Inspection							Date: 01 / 03 / 2023	
Site Name: Dazed BDZ Federal Com #002								
API Number: 30-0 15 33428		Plug Date: 11 / 02 / 2021		Program: <input checked="" type="radio"/> Initial <input type="radio"/> Final		Monitoring Corrective		
Was this the last remaining or only well on the location?							YES	NO
Are there any abandoned pipelines that are going to remain on the location?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that are going to remain on location?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
If any production equipment or structure (including 3rd party) is to remain on location, please specify. 3rd party risers on north side of location by the road.								
Site Evolution								
Recontoured back to original State/Topsoil Replaced							YES	NO
Have the rat hole and cellar been filled and leveled?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Have the cathodic protection holes been properly abandoned & reclaimed?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Rock or Caliche Surfacing materials have been removed?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Section Comments:								
All Facilities Removed for Final Remediation								
Have all of the pipelines & production equipment been cleared? (other than the listed above)							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Has all of the required junk and trash been cleared from the location?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Have all of the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Have all of the required metal bolts and other materials have been removed?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Have all the required portable bases been removed?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Section Comments:								
Dry Hole Marker							YES	NO
Has a steel marker been installed per COA requirements?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Check One: <input type="checkbox"/> Buried <input checked="" type="checkbox"/> Above Ground								
DHM Info	Operator Name	Lease Name & Number	UL-S-T-R	Qtr Section (Footage)	API #	Federal Lease # (Federal Only)		
Met	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
Not Met								
Free of Oil or Salt Contaminated Soil							YES	NO
Have all the required pits been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Have all other environmental concerns been addressed as per OCD rules?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
If any environmental concerns remain on the location, please specify.								
Abandoned Pipelines							YES	NO
Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 29. 15. 35. 10 NM4C).							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Have all fluids have been removed from any abandoned pipelines?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Have all abandoned pipelines been confirmed to NOT contain additional regulated NORM, other than that which accumulated under normal operation?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Have all accessible points of abandoned pipelines been permanently capped?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Section Comments:								
Last Remaining or Only Well on the Location							YES	NO
Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Have all electrical service poles and lines been removed from the location?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Is there any electrical utility distribution infrastructure that is remaining on the location?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Have all the retrievable pipelines, production equipment been removed from the location?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Has all the junk and trash been removed from the location?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Section Comments:								
Environmental Only - Do not have to be met to pass inspection							Met	Not Met
This section corresponds with questions on the Reclamation Inspection Form in Environmental but not related to NMOC forms.							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Free of Noxious or Invasive Weeds? (Note species or treatment in remarks)							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Site Stability? Erosion controls in place (if necessary) & working.							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Signs of seedling completion? (Broadcast/Drilled)							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Revegetation Success as compared to background? Met >75% Circle One: <input checked="" type="radio"/> 0% <input type="radio"/> 25% <input type="radio"/> 50% <input type="radio"/> 75% <input type="radio"/> 100%							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Adequate Reclamation Fence Installed?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Section Comments:								
Additional Findings or Comments:								
Inspector: Igor Rios								
Picture Checklist: <input checked="" type="checkbox"/> DHM <input checked="" type="checkbox"/> Site Corners <input checked="" type="checkbox"/> Background <input checked="" type="checkbox"/> Access Road <input checked="" type="checkbox"/> 3rd Party Equipment <input type="checkbox"/> Contamination <input type="checkbox"/> EOG Equipment <input type="checkbox"/> Trash/Junk								
Inspection Result							<input checked="" type="radio"/> PASS	<input type="radio"/> FAIL

On-Site Inspection_Form v1.xlsx

10/20/2022

Well Name: DAZED BDZ FEDERAL COM	Well Location: T21S / R24E / SEC 3 / LOT 13 / SWNW /	County or Parish/State: EDDY / NM
Well Number: 2	Type of Well: CONVENTIONAL GAS WELL	Allottee or Tribe Name:
Lease Number: NMNM0230377B	Unit or CA Name: 2 DAZED BDZ FEDERAL COM	Unit or CA Number: NMNM112721
US Well Number: 300153342800X2	Well Status: Abandoned	Operator: EOG RESOURCES INCORPORATED

Notice of Intent

Sundry ID: 2658417

Type of Submission: Notice of Intent

Date Sundry Submitted: 02/23/2022

Date proposed operation will begin: 08/23/2022

Type of Action: Reclamation

Time Sundry Submitted: 07:22

Procedure Description: EOG Resources, Inc. is requesting approval to proceed with Reclamation activity as shown in green, yellow and brown on attached map with 3rd party company, Lucid Energy/Durango, taking responsibility for their equipment removal and Reclamation of that area as shown in red on the map. Please see attached correspondence. Thank you.

NOI Attachments

Procedure Description

- Dazed_BDZ_Federal_Com_2__Reclamation_3rd_Party_Equipment__20220223072221.pdf
- Durango_Email_10_25_21_20220223072221.pdf

Well Name: DAZED BDZ FEDERAL COM	Well Location: T21S / R24E / SEC 3 / LOT 13 / SWNW /	County or Parish/State: EDDY / NM
Well Number: 2	Type of Well: CONVENTIONAL GAS WELL	Allottee or Tribe Name:
Lease Number: NMNM0230377B	Unit or CA Name: 2 DAZED BDZ FEDERAL COM	Unit or CA Number: NMNM112721
US Well Number: 300153342800X2	Well Status: Abandoned	Operator: EOG RESOURCES INCORPORATED

Operator Certification

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a submission of Form 3160-5 or a Sundry Notice.


Operator Electronic Signature: TINA HUERTA	Signed on: FEB 23, 2022 07:22 AM
Name: EOG RESOURCES INCORPORATED	
Title: Regulatory Specialist	
Street Address: 104 SOUTH FOURTH STREET	
City: Artesia	State: NM
Phone: (575) 748-4168	
Email address: tina_huerta@eogresources.com	

Field Representative

Representative Name:		
Street Address:		
City:	State:	Zip:
Phone:		
Email address:		

BLM Point of Contact

BLM POC Name: JAMES A AMOS	BLM POC Title: Acting Assistant Field Manager
BLM POC Phone: 5752345927	BLM POC Email Address: jamos@blm.gov
Disposition: Approved	Disposition Date: 04/07/2022
Signature: James A. Amos	



Meter & equipment removal request



Heather Treffert

To Tom Cleveland; Measurement Data; Chris Fuentes; Frankie Soto; Jason Fuentes
Cc Christopher Gurule; Bob Asher; Kane Horner

Reply Reply All Forward

Mon 10/25/2021 8:08 AM

Good Morning!

The following wells have been plugged and we are requesting the meters and equipment be disconnected and removed.

12817	Box Canyon 34 BAB Fed #1
9319	Dazed BDZ Fed Com #2
410	Richard Knob AEX State #1

Thanks!

Heather Treffert
EOG Resources, Inc
Artesia Division
104 South 4th Street
Artesia, NM 88210
Office Phone: (575) 748-4232
Cell Phone: (575) 689-5332
Email: Heather.Treffert@eogresources.com



District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 230294

CONDITIONS

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 230294
	Action Type: [C-103] Sub. General Sundry (C-103Z)

CONDITIONS

Created By	Condition	Condition Date
dmcclure	ACCEPTED FOR RECORD	9/29/2023