

Well Name: FEDERAL HQ	Well Location: T20S / R22E / SEC 32 / NWNE /	County or Parish/State: EDDY / NM
Well Number: 3	Type of Well: CONVENTIONAL GAS WELL	Allottee or Tribe Name:
Lease Number: NMNM21012	Unit or CA Name:	Unit or CA Number:
US Well Number: 300153570400X1	Well Status: Abandoned	Operator: EOG RESOURCES INCORPORATED

Subsequent Report

Sundry ID: 2682774

Type of Submission: Subsequent Report

Type of Action: Reclamation

Date Sundry Submitted: 07/19/2022

Time Sundry Submitted: 10:56

Date Operation Actually Began: 10/13/2021

Actual Procedure: Please see attached Surface Reclamation Complete Report and Annual Surface Reclamation Monitoring Report. This is all NMSLO surface with Federal mineral. EOG will conduct 2nd annual monitoring in October 2022 and will submit a sundry advising of the status of reclamation success. Upon meeting NMSLO's success criteria, a Final Abandonment Notice will be submitted.

SR Attachments

Actual Procedure

Federal_HQ__003_CRR_7.12.22_20220719105549.pdf

Well Name: FEDERAL HQ

Well Location: T20S / R22E / SEC 32 / NWNE /

County or Parish/State: EDDY / NM

Well Number: 3

Type of Well: CONVENTIONAL GAS WELL

Allottee or Tribe Name:

Lease Number: NMNM21012

Unit or CA Name:

Unit or CA Number:

US Well Number: 300153570400X1

Well Status: Abandoned

Operator: EOG RESOURCES INCORPORATED

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: TINA HUERTA

Signed on: JUL 19, 2022 10:56 AM

Name: EOG RESOURCES INCORPORATED

Title: Regulatory Specialist

Street Address: 104 SOUTH FOURTH STREET

City: Artesia

State: NM

Phone: (575) 748-4168

Email address: tina_huerta@eogresources.com

Field

Representative Name:

Street Address:

City:

State:

Zip:

Phone:

Email address:

BLM Point of Contact

BLM POC Name: DEBORAH L MCKINNEY

BLM POC Title: Legal Instruments Examiner

BLM POC Phone: 5752345931

BLM POC Email Address: dmckinne@blm.gov

Disposition: Accepted

Disposition Date: 10/14/2022

Signature: Deborah McKinney



**Surface Reclamation Complete Report
&
Annual Surface Reclamation Monitoring Report**

Well Name: Federal HQ #3

API: 30-015-35704

Well Location: Section 32, T20.5S-R22E; Eddy County New Mexico

Surface Owner: State

Reclamation Complete Date: 10/13/2021

Reclamation Annual Monitoring Date: 10/13/2022

Total Acres reclaimed: 2.10 acres

Seed Mix:

Mix	Species	lb/acre (Drilled)	lb/acre (Broadcast)
BLM #1 (For Loamy Soils)	Plains lovegrass	1.0	2.0
"	Sand dropseed	2.0	4.0
"	Sideoats grama	10.0	20.0
"	Plains Bristlegrass	4.0	8.0

Weights should be as pounds of pure live seed.

Note:

EOG will conduct an annual surface reclamation monitoring field visit in 2022 to determine if successful vegetation regrowth is established.





NMOCD / C-103Q Submission Checklist Questions		
Well Name: FEDERAL HQ 003		
Subsequent Report of Location Ready for OCD Inspection After P&A		
For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application: lease and well location, hereinafter "location"; flowlines or pipelines, hereinafter "pipeline"; and non-retrieved or abandoned, hereinafter "abandoned";		
	YES	NO
Was this the last remaining or only well on the location?	X	
Are there any abandoned pipelines that are going to remain on the location?		X
Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that are going to remain on location? If any production equipment or structure is to remain on location, please specify. BRD PARTY RISER & EQUIPMENT	X	
Site Evaluation		
Please answer all questions in this group.		
Have all the required pits been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?	X	
Have the rat hole and celler been filled and leveled?	X	
Have the cathodic protection holes been properly abandoned?	X	
Has a steel marker, at least 4 inches in diameter and at least 4 feet above ground level, been set in concrete?	X	
The (concrete-set) steel marker shows: Must attach marker photograph(s).*		
THE OPERATOR NAME, LEASE NAME AND WELL NUMBER AND LOCATION, INCLUDING UNIT LETTER, SECTION, TOWNSHIP, AND RANGE, SHALL BE WELDED, STAMPED OR OTHERWISE PERMANENTLY		
Have all of the required pipelines and other production equipment been cleared?	X	
Has all of the required junk and trash been cleared from the location?	X	
Have all of the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level?	X	
Have all of the required metal bolts and other materials have been removed?	X	
Poured onsite concrete do not have to be removed.	X	
Have all the required portable bases been removed?	X	
Have all other environmental concerns been addressed as per OCD rules?	X	
If any environmental concerns remain on the location, please specify.		
*Proof of the site marker (photograph) is required Please submit any other site photographs that would assist in documenting the above answers, site features, additional concerns, or other nearby / remaining structures and equipment.		
Abandoned Pipelines		
Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19. 15. 35. 10 NMAC).		
Have all fluids have been removed from any abandoned pipelines?		
Have all abandoned pipelines been confirmed to <u>NOT</u> contain additional regulated NORM, other than that which accumulated under normal operation?		
Have all accessible points of abandoned pipelines been permanently capped?		
Last Remaining or Only Well on the Location		
Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.		
Have all electrical service poles and lines been removed from the location?	X	
Is there any electrical utility distribution infrastructure that is remaining on the location?	X	
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?	X	
Have all the retrievable pipelines, production equipment been removed from the location?	X	
Has all the junk and trash been removed from the location?	X	

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 151585

CONDITIONS

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 151585
	Action Type: [C-103] Sub. General Sundry (C-103Z)

CONDITIONS

Created By	Condition	Condition Date
dmcclosure	ACCEPTED FOR RECORD	9/29/2023