

Office  
 District I – (575) 393-6161  
 1625 N. French Dr., Hobbs, NM 88240  
 District II – (575) 748-1283  
 811 S. First St., Artesia, NM 88210  
 District III – (505) 334-6178  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 District IV – (505) 476-3460  
 1220 S. St. Francis Dr., Santa Fe, NM  
 87505

State of New Mexico  
 Energy, Minerals and Natural Resources

Form C-103  
 Revised July 18, 2013

OIL CONSERVATION DIVISION  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-42448
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator OWL SWD Operating LLC		6. State Oil & Gas Lease No.
3. Address of Operator 8201 Preston Rd, Suite 520; Dallas, TX 75225		7. Lease Name or Unit Agreement Name Madera SWD
4. Well Location Unit Letter <u>      </u> N <u>      </u> : <u>      </u> 433 <u>      </u> feet from the <u>      </u> South <u>      </u> line and <u>      </u> 1970 <u>      </u> feet from the <u>      </u> West <u>      </u> line Section <u>      </u> 11 <u>      </u> Township <u>      </u> 24 S <u>      </u> Range <u>      </u> 34 E <u>      </u> NMPM <u>      </u> County Lea		8. Well Number #1
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3464' GR		9. OGRID Number 308339
		10. Pool name or Wildcat SWD; Devonian (96101)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
DOWNHOLE COMMINGLE <input type="checkbox"/>	P AND A <input type="checkbox"/>
CLOSED-LOOP SYSTEM <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

8/27/21 MIRU WLU. No psi on well. RIH with spinner/temp survey tools to 10,200'. Appears to be possible parted injection string at 48'. POOH, RDMO.

9/1/21 MIRU WLU. No psi on well. RIH w/ 4.40" gauge ring run. Could not get past 47' after multiple attempts with different size gauge rings. POOH, RDMO.

9/12/21 MIRU WSU. No psi on well. ND wellhead, NU BOP, function test. Torque down and prepare for running fishing tools tomorrow.

9/13/21 No psi on well. TIH w/ overshot, latched onto fish top. Pulled out 16' of 5.5" injection string. TIH with impression block and tagged at 48'. POOH and wait on casing crew equipment to be repaired. SDFN.

9/14/21 No psi on well. Casing crew arrived w/ wrong equipment. TIH, tag top of fish and dress. POOH and lay down BHA/DC's. Waiting on casing crew. SDFN.

9/15/21 No psi on well. TIH w/ overshot, latched onto fish top. POOH and lay down fishing tools. Fish consisted of 4 jts (42', 40', 43', 42'). 2 split collars on joints. Total length of fish 167'. Total retrieved to date is 183'. SDFN

9/16/21 No psi on well. Change out 5.5" rams for 2 7/8" rams. Function test. TIH with 7 jts (2 7/8 PH6) & overshot. Tagged fish top at 225', pulled into pipe working up to 40k overpull. Release from fish and POOH laying down. Swap rams back to 5.5". PU/MU overshot and 5.5" tubing. TIH w/ overshot tools, tag fish at 225'. Worked over fish top, overpull 32k. Stabbed in TIW valve. SDFN.

9/17/21 No psi on well. PU/MU 5 1/8" gate valve, stabbed onto 5.5" tubing, setup floor for WL operations. PU/MU WL tools for gauge ring run (4.40"). RIH and tag pkr at 17,300'. POOH w/ WL. POOH w/ fishing string. SDFN.

9/18/21 No psi on well. ND BOP, NU wellhead. RDMO. Waiting for drilling rig to pull remaining 5.5" #20&23 injection string.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Lucas Sheward TITLE Operations Engineer DATE 10/8/21

Type or print name Lucas Sheward E-mail address: lsheward@oilfieldwaterlogistics.com PHONE: 432-242-8991

**For State Use Only**

APPROVED BY: Kerry Fortner TITLE Compliance Officer A DATE 10/3/23

Conditions of Approval (if any):

Office  
 District I – (575) 393-6161  
 1625 N. French Dr., Hobbs, NM 88240  
 District II – (575) 748-1283  
 811 S. First St., Artesia, NM 88210  
 District III – (505) 334-6178  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 District IV – (505) 476-3460  
 1220 S. St. Francis Dr., Santa Fe, NM  
 87505

State of New Mexico  
 Energy, Minerals and Natural Resources

Form C-103  
 Revised July 18, 2013

OIL CONSERVATION DIVISION  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-42448
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator OWL SWD Operating LLC		6. State Oil & Gas Lease No.
3. Address of Operator 8201 Preston Rd, Suite 520; Dallas, TX 75225		7. Lease Name or Unit Agreement Name Madera SWD
4. Well Location Unit Letter <u>  N  </u> : <u>  433  </u> feet from the <u>  South  </u> line and <u>  1970  </u> feet from the <u>  West  </u> line Section <u>  11  </u> Township <u>  24 S  </u> Range <u>  34 E  </u> NMPM County Lea		8. Well Number #1
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3464' GR		9. OGRID Number 308339
		10. Pool name or Wildcat SWD; Devonian (96101)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
DOWNHOLE COMMINGLE <input type="checkbox"/>	P AND A <input type="checkbox"/>
CLOSED-LOOP SYSTEM <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

8/27/21 MIRU WLU. No psi on well. RIH with spinner/temp survey tools to 10,200'. Appears to be possible parted injection string at 48'. POOH, RDMO.

9/1/21 MIRU WLU. No psi on well. RIH w/ 4.40" gauge ring run. Could not get past 47' after multiple attempts with different size gauge rings. POOH, RDMO.

9/12/21 MIRU WSU. No psi on well. ND wellhead, NU BOP, function test. Torque down and prepare for running fishing tools tomorrow.

9/13/21 No psi on well. TIH w/ overshot, latched onto fish top. Pulled out 16' of 5.5" injection string. TIH with impression block and tagged at 48'. POOH and wait on casing crew equipment to be repaired. SDFN.

9/14/21 No psi on well. Casing crew arrived w/ wrong equipment. TIH, tag top of fish and dress. POOH and lay down BHA/DC's. Waiting on casing crew. SDFN.

9/15/21 No psi on well. TIH w/ overshot, latched onto fish top. POOH and lay down fishing tools. Fish consisted of 4 jts (42', 40', 43', 42'). 2 split collars on joints. Total length of fish 167'. Total retrieved to date is 183'. SDFN

9/16/21 No psi on well. Change out 5.5" rams for 2 7/8" rams. Function test. TIH with 7 jts (2 7/8 PH6) & overshot. Tagged fish top at 225', pulled into pipe working up to 40k overpull. Release from fish and POOH laying down. Swap rams back to 5.5". PU/MU overshot and 5.5" tubing. TIH w/ overshot tools, tag fish at 225'. Worked over fish top, overpull 32k. Stabbed in TIW valve. SDFN.

9/17/21 No psi on well. PU/MU 5 1/8" gate valve, stabbed onto 5.5" tubing, setup floor for WL operations. PU/MU WL tools for gauge ring run (4.40"). RIH and tag pkr at 17,300'. POOH w/ WL. POOH w/ fishing string. SDFN.

9/18/21 No psi on well. ND BOP, NU wellhead. RDMO. Waiting for drilling rig to pull remaining 5.5" #20&23 injection string.

Spud Date:

Rig Release Date:

---

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Lucas Sheward TITLE Operations Engineer DATE 10/8/21

Type or print name Lucas Sheward E-mail address: lsheward@oilfieldwaterlogistics.com PHONE: 432-242-8991

**For State Use Only**

APPROVED BY: \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

Conditions of Approval (if any):

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS  
  
Action 54929

CONDITIONS

Operator: OWL SWD OPERATING, LLC 20 Greenway Plaza Houston, TX 77046	OGRID: 308339
	Action Number: 54929
	Action Type: [C-103] Sub. Workover (C-103R)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	10/3/2023