

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name
MORNING STAR PARTNERSAPI Number
30-025- 03089Property Name
Central Vacuum UnitWell No.
96

U. Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
B	06	185	35E	660	N	1980	E	LEA

Well Status

YES	NO	YES	NO	INJ	SWD	PRODUCER	DATE
							9-8-23

OBSERVED DATA

	(A) Surface	(B) Inter m(1)	(C) Inter m(2)	(D) Prod Casing	(E) Tubing
Pressure	0	0	0	112 psi	300 psi
Flow Characteristics:					
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WIR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injects for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood or
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:	<i>Raul Gonzales</i>	OIL CONSERVATION DIVISION Entered into RBDMS Re-test
Printed name:	Raul Gonzales	
Title:	LEASE OPERATOR	
E-mail Address:	@CTFIELDVCS.COM	
Date:	9/8/23	
Phone:		
Witness:		

INSTRUCTIONS ON BACK OF THIS FORM

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 289076

CONDITIONS

Operator: MorningStar Operating LLC 400 W 7th St Fort Worth, TX 76102	OGRID: 330132
	Action Number: 289076
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/4/2023