

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name MORNING STAR PARTNERS	API Number 30-025-25703
Property Name CENTRAL VACUUM UNIT	Well No. 40


Surface Location									
UT Lat D	Section 36	Township 17S	Range 34E		Feet from 42	N/S Line N	Feet from 1247	E/W Line W	County LEA

Well Status									
TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR NO	SWD	OIL	PRODUCER	GAS	DATE 6-15-23

OBSERVED DATA

	(A)Surface	(B)Intern(1)	(C)Intern(2)	(D)Prod.Case	(E)Tubing
Pressure	0			0	1400
Flow Characteristics					
Puff	Y	N	N	N	CO2 X
Steady Flow	Y	N	N	N	WTR
Surges	Y	N	N	N	GAS
Down to nothing	Y	N	N	N	Interval Flow
Gas or Oil	Y	N	N	N	Interval Rate
Water	Y	N	N	N	Interval Pressure

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature 	OIL CONSERVATION DIVISION
Printed name ENRIQUE CARMONA	Entered into RBDMS
Title LEASE OPERATOR	Re-test
E-mail Address ECARMONA@CTFIELDVCS.COM	
Date 6-15-23	
Phone 682-404-3181	
Address	

INSTRUCTIONS ON BACK OF THIS FORM

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 289029

CONDITIONS

Operator: MorningStar Operating LLC 400 W 7th St Fort Worth, TX 76102	OGRID: 330132
	Action Number: 289029
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/4/2023