Received by OCD: 2/5/2024 11:08:29 AM OfficeState of New MexicoDistrict I– (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 District III – (575) 748-1283 811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505State of New Mexico Energy, Minerals and Natural Resources0IL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505State of New Mexico Energy, Minerals and Natural Resources	WELL API NO. 20.025 43470	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other: Acid Gas Injection Well	7. Lease Name or Unit Agreement Name Monument AGI D 8. Well Number #2	
2. Name of Operator Targa Midstream Services LLC 3. Address of Operator	9. OGRID Number 24650 10. Pool name or Wildcat	
1000 Louisiana, Houston, TX 77002 4. Well Location	AGI: Devonian	
Unit Letter O: 685 feet from the SOUTH line and 2,362 feet from the EAST line Section 36 Township 19S Range 36E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,384 (GR)		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK		PLUG AND ABANDON		REMEDIAL WORK ALTER	RING CASING
TEMPORARILY ABANDON		CHANGE PLANS		COMMENCE DRILLING OPNS.) A 🗌
PULL OR ALTER CASING		MULTIPLE COMPL		CASING/CEMENT JOB	
DOWNHOLE COMMINGLE					
CLOSED-LOOP SYSTEM				OTHER: (Mechanical Integrity Test)	\boxtimes
OTHER: (COMPLETION)					


13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC.

The mechanical integrity test (MIT) was conducted on Thursday, January 18, 2024. Gary Robinson (NMOCD) was on-site to oversee and approve the MIT and bradenhead test (BHT). Initial Annular Pressures – Surface/Intermediate: 485 psi, Intermediate/Production: 407 psi, Production/Tubing: 516 psi, Tubing: 1,643 psi while injecting 68 mscfd treated acid gas (TAG). Below is a step-by-step summary with results:

- 1. At 9:50 am (MT) the intermediate and surface casing annular spaces were bled down completely to the atmosphere (see BHT) and lines from the diesel pump truck and a calibrated chart recorder were attached to the production annular space well valve to record pressure changes during the MIT. The diesel from the production annular space was completely bled into the pump truck and at 10:31 am the chart recorder was started.
- 2. At 10:35 am diesel was slowly added from the pump truck to achieve the beginning test pressure. The well and chart recorder was then isolated from the truck and the MIT began at 10:36 am with the annular pressure at 610 psi.
- 4. The chart recorded the annular pressure until 11:13 am (37 minutes). Diesel was then bled back to 0 psi and the chart was removed from the recorder. An operating pressure of 300 psi was then added to the annular space.
- 5. During the test, the annular pressure dropped from 610 to 580 psi, a decrease of 30 psi (4.9%), but remained consistent for the final 25 minutes. The surface and intermediate casing valves were closed following the MIT.


The MIT pressure chart, BHT documentation, well bore diagram, and chart recorder calibration sheet are attached.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
SIGNATURE Dale T Live, In	TITLE <u>Consultant to Targa Midstream LLC</u>	DATE <u>1-19-24</u>				
Type or print name Dale T. Littlejohn	E-mail address: dale@geolex.com	PHONE: <u>505-842-8000</u>				
For State Use Only APPROVED BY: <u>Juny</u> Fortner Conditions of Approval (if any):	TITLE Compliance Officer A	DATE 2/6/24				



<u>Diadid I</u> 1523 N. French Do., Hobbs, NN 83240 Phone: (S7S) 393-6151 Fax. (57S) 393-0729


State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office



Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies. Surf-blew to zero in 30min. 20min 1/2" valve - 10min 2" valve Int-blew to zero in 5 min thro 12" needle raive Pid-blew to zerointotrk in 3min.

ないため

gnature:		
• •	OIL CONSERVATION DIVISION	
inted name:	Entered into RBDMS	
tle:	Re-test	
mail Address:	Ma	
ate: Phone: 0/ 01	. A	
Witness: x Mar Aleman		
Witness: Slelef Colinson		



•

MACLASKEY
OILFIELD SERVICES
5900 WEST LOVINGTON HWY. HOBBS, N.M. 88240 505-393-1016
THIS IS TO CERTIFY THAT: DATE 1824
I. 19/6: 160/10/2000 METER TECHNICAN FOR MACLASKEY OILFIELD SERVICES, INC. HAS CHECKED THE CALIBRATION ON THE FOLLOWING INSTRUMENT
SERIAL NUMBER
520-7150-1500
TESTED AT THESE POINTS. PRESSURE <u>FOO</u> PRESSURE <u>FOO</u>
TEST AS FOUND CORRECTED TEST AS FOUND CORRECT $\begin{array}{cccccccccccccccccccccccccccccccccccc$
REMARKS:
SIGNED: Albert Palaiscon
SIGNED. FFILM PARALICE

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
TARGA MIDSTREAM SERVICES LLC	24650
811 Louisiana Street	Action Number:
Houston, TX 77002	311225
	Action Type:
	[C-103] Sub. General Sundry (C-103Z)

CONDITIONS

Created By		Condition Date
kfortner	None	2/6/2024

CONDITIONS

Page 6 of 6

Action 311225