

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-23-2024 Operator Maralex Resources API #30-045- 33875
Property Name Trading Post Well No. 35-2 Location: Unit C Section 35 Township 5N Range 11W
Well Status(Shut-In or Producing) Initial PSI: Tubing 5 Intermediate 5 Casing 30 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	Bradenhead BH	Int	Csg	Int	Csg
5 min	0		30		
10 min	0		30		
15 min	0		30		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE X

REMARKS:

No Leaks

By Gavin Johnson

Witness _____

Mechanic/Pumper _____
(Position)

E-mail address gjohnson@xuhoo.com

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 355622

CONDITIONS

Operator: MARALEX RESOURCES INC P.O. Box 338 Ignacio, CO 81137	OGRID: 13998
	Action Number: 355622
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
mkuehling	None	8/22/2024