

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name <i>Rover Operating LLC</i>	³ API Number <i>30-015-21487</i>
Property Name <i>Artesia State Unit</i>	Well No. <i>701</i>

⁷ Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
<i>B</i>	<i>23</i>	<i>185</i>	<i>27E</i>	<i>10</i>	<i>FNL</i>	<i>2580</i>	<i>FBL</i>	<i>EDdy</i>

Well Status

TA'D Well	SHUT-IN	INJECTOR	PRODUCER	DATE
YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> INJ SWD	OIL <input type="checkbox"/> GAS <input type="checkbox"/>	<i>9/1/2022</i>

OBSERVED DATA

	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure	<i>0</i>			<i>0</i>	<i>0</i>
Flow Characteristics					
Puff	Y/ <input checked="" type="checkbox"/> N	Y/N	Y/N	<input checked="" type="checkbox"/> Y/N	CO2 _____
Steady Flow	Y/ <input checked="" type="checkbox"/> N	Y/N	Y/N	Y/ <input checked="" type="checkbox"/> N	WTR <input checked="" type="checkbox"/>
Surges	Y/ <input checked="" type="checkbox"/> N	Y/N	Y/N	Y/ <input checked="" type="checkbox"/> N	GAS _____
Down to nothing	<input checked="" type="checkbox"/> Y/N	Y/N	Y/N	<input checked="" type="checkbox"/> Y/N	If applicable type
Gas or Oil	Y/ <input checked="" type="checkbox"/> N	Y/N	Y/N	Y/ <input checked="" type="checkbox"/> N	fluid injected for
Water	Y/ <input checked="" type="checkbox"/> N	Y/N	Y/N	Y/ <input checked="" type="checkbox"/> N	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR <input type="checkbox"/>	FRESH <input type="checkbox"/>	SALTY <input type="checkbox"/>	SULFUR <input type="checkbox"/>	BLACK <input type="checkbox"/>
--------------------------------	--------------------------------	--------------------------------	---------------------------------	--------------------------------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

BHT-OK

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION
Printed name: Danny Smolik	Entered RBDMS
Title: Compliance Office	Re-test
E-mail Address: danny.smolik@state.nm.us	
Date: <i>9/1/2022</i>	Phone: 575-626-0836
Witness: <i>[Signature]</i>	

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 142095

CONDITIONS

Operator: ROVER OPERATING, LLC 2024 W. 15th St. Plano, TX 75075	OGRID: 371484
	Action Number: 142095
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	9/5/2024