## State Of New Mexico Energy, Minerals and Natural Resources Department

19-Sep-24

## HILCORP ENERGY COMPANY

**Pre Enforcement Notification** 

1111 Travis Street Houston, TX 77002

## Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the Compliance Officer copied on this letter, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

## INSPECTION DETAIL SECTION

[30-045-33444] J C GORDON D #002F		OGRID: 372171	F-22-27N-10W 2330 FNL 1575 FWL	
Inspection Date	Type Inspection	Inspector	Inspection No.	
9/19/2024	Routine Inspection	[EZM] Eileen Medrano	iEZM2426344598	
Violation Title				Corrective Action Due
cEZM2426357759 19.15.29 Releases Surface Leaks/Spills				12/18/2024
(The loca	ation has staining by the com	pressor that needs to be remo	oved.)	
cEZM2426357760 19.15.17 Pits, Closed-Loop Systems, Below Grade Tanks and Sumps Noncompliance with Requirements (Construction, Operations or Closure)				12/18/2024
(The belo	ow grade tank contains hydro	carbons that need to be remo	ved.)	
cEZM2426357761 19.15.16.8 Sign on Wells Inaccurate Information				12/18/2024
(The loca	ation well sign is missing the i	equired quarter/quarter or un	it letter information and needs to be updat	ed.)

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

Oil Conservation Division \* 1000 Rio Brazos Road \* Aztec, NM 87410 Phone: 505-334-6178 \* Fax: 505-334-6170 \* www.emnrd.nm.gov