District 2 Artesia

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name	API Number
BxP	30-025-11450

Property Name	Well No.
Langlie Jal Unit	#64

Surface Location

UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
O	05	25S	37E		660	S	1980	E	LEA

Well Status

TA'D WELL		SHUT-IN		INJECTOR		PRODUCER		DATE
YES (NO)	YES	(NO)	(INJ)	SWD	OIL	GAS	PRODUCER	7-18-2023

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0			O	575
Flow Characteristics					
Puff	Y / (N)	Y / N	Y / N	Y / (N)	CO2 ____ ✓
Steady Flow	Y / (N)	Y / N	Y / N	Y / (N)	WTR ✓
Surges	Y / (N)	Y / N	Y / N	Y / (N)	GAS ___
Down to nothing	(Y) / N	Y / N	Y / N	(Y) / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / (N)	Y / N	Y / N	Y / (N)	
Water	Y / (N)	Y / N	Y / N	Y / (N)	

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Ryan Marti	OIL CONSERVATION DIVISION
Printed name: Ryan Martin	Entered into RBDMS
Title: AGENT	Re-test
E-mail Address: Mymerch@Penrocoil.Com	
Date: 9/18/23 Phone: 575-492-1236	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

16

CONDITIONS

Action 258562

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
BXP Operating, LLC 11757 KATY FREEWAY HOUSTON, TX 77079	329487
	Action Number: 258562
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	11/27/2024