

Office
 District I – (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II – (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III – (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV – (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM
 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised July 18, 2013

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-021-20534
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name WEST BRAVO DOME UNIT
8. Well Number #141J
9. OGRID Number 16696
10. Pool name or Wildcat [96387] WEST BRAVO DOME CO2 GAS

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other CO2	
2. Name of Operator OXY USA INC	
3. Address of Operator P.O. BOX 4294 HOUSTON, TX 77210	
4. Well Location	
Unit Letter J : 1750 feet from the SOUTH line and 1700 feet from the EAST line	
Section 14 Township 19N Range 29E NMPM County HARDING	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPL <input type="checkbox"/> DOWNHOLE COMMINGLE <input type="checkbox"/> CLOSED-LOOP SYSTEM <input type="checkbox"/> OTHER: <input type="checkbox"/>		SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input checked="" type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>	
--	--	--	--

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

THE FINAL WELLBORE AND PA JOB NOTES ARE ATTACHED.

CUT AND CAP WAS COMPLETE ON 2/24/2025.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE REGULATORY ENGINEER DATE 3/4/2025

Type or print name STEPHEN JANACEK E-mail address: STEPHEN_JANACEK@OXY.COM PHONE: 713-493-1986

For State Use Only

APPROVED BY: _____ TITLE _____ DATE _____

Conditions of Approval (if any):



TD @	-	MD
TD @	2122'	TVD
PBTD @	-	MD

WEST BRAVO DOME UNIT #141J**30-021-20534****PA JOB NOTES**

Start Date	Remarks
2/11/2025	ROAD AXIS 1145 F/ BDU 301 TO WBDU 141J, WORK OVER DETAINED DUE TO HEAVY FOG.
2/11/2025	SPOT IN PLUGGING PACKAGE.
2/11/2025	CREW TRAVELED TO CAMP
2/12/2025	CREW TRAVEL TO WBDU 141J
2/12/2025	HTGSM, DISCUSS HAND AND FINGER PLACEMENT.
2/12/2025	WAIT ON WEATHER TO CLEAR UP TO MOVE WORK OVER TO WBDU 141J. WEATHER DID NOT SHOW SIGNS OF CLEARING UP.
2/12/2025	CREW TRAVELED TO YARD
2/16/2025	CREW TRAVELED F/ YARD TO WBDU 141J
2/16/2025	HTGSM, DISCUSS HAND AND FINGER PLACEMENT.
2/16/2025	ROAD IN AXIS 1145 TO WBDU 141J
2/16/2025	SION
2/16/2025	CREW TRAVELED TO CAMP
2/17/2025	CREW TRAVELED TO WBDU 141J
2/17/2025	HTGSM, DISCUSS HAND AND FINGER PLACEMENT.
2/17/2025	R/U WORK OVER AND PLUGGING PACKAGE.
2/17/2025	CHECK TBG "100", CSG AND SURF PRESSURE "0"
2/17/2025	NIPPLE DOWN WELL HEAD. SIEZED STUDS ON WELL HEAD.
2/17/2025	NIPPLE UP BOP AND ADAPTER SPOOL
2/17/2025	RIG UP WORKING FLOOR AND HANDLING TOOLS
2/17/2025	SET AND TEST COFO "OK"
2/17/2025	WORK TO USET PACKER, J-OFF OF PACKER L/D FIBERGLASS TBG 64 JTS.
2/17/2025	P/U 2-3/8 WORK STRING 61 JTS. LATCH ON TO AND UNSET PACKER.
2/17/2025	POOH W/ 30 STANDS TO DERRICK. PACKER DRAGGING DURING OPERATIONS.
2/17/2025	M/U CICR, RIH AND SET @ 1971 W/ 61 JTS AND 6FT PUP (DEPTH PER NM OCD)
2/17/2025	P/U CMT PUMP, PLUG 1) SQZ 20SX FROM 2618' TO 1971', 4.7 BBLS. 14.8# 1.32 YIELD. DISP TO 1971 W/ 7.4 BBLS F/W
2/17/2025	CIRC WELL W/ 50 BBLS F/W FOR CBL IN THE MORNING.
2/17/2025	POOH 31 STDs TO DERRICK
2/17/2025	WINTERIZE RIG FOR OVERNIGHT TEMPS. SION
2/17/2025	CREW TRAVELED TO CAMP
2/18/2025	CREW TRAVELED TO WBDU 141J
2/18/2025	HTGSM, DISCUSS HAND AND FINGER PLACEMENT.
2/18/2025	CHECK TBG AND CSG PRESSURE "0"
2/18/2025	SET AND TEST COFO "OK"
2/18/2025	R/U RENEGADE WIRELINE.
2/18/2025	BUILD AND PROGRAM CBL

	(RENEGADE WIRELINE DOWN TIME) BEGIN RIH W/ CBL. POOH DUE TO NO COMMUNICATION. TROUBLE SHOOT ISSUE ON LOCATION, COLD CALLED FOR PARTS. PARTS ARRIVED @ 1500HRS.
2/18/2025	BUILD AND PICK UP TOOLS
2/18/2025	RIH W/ CBL. TAG CICR @ 1971, RUN CBL F/ 1971-0, R/D WIRELINE
2/18/2025	R/D WIRELINE
2/18/2025	RIH W/ 61 JTS. TO 1971.
2/18/2025	(AXIS DOWN TIME) R/U CMT PUMP ATTEMPT TO TURN ON BATCH MIXER. (MECHANICS EN ROUTE)
2/18/2025	WINTERIZE RIG FOR OVER NIGHT TEMPS, SION
2/18/2025	CREW TRAVELED TO CAMP
2/19/2025	CREW TRAVELED TO WBDU 141J
2/19/2025	HTGSM, DISCUSS HAND AND FINGER PLACEMENT.
2/19/2025	CHECK TBG AND CSG PRESSURE "0"
2/19/2025	SET AND TEST COFO "OK"
2/19/2025	(AXIS DOWN TIME) ATTEMPT TO TURN ON BATCH MIXER. FOUND PROBLEMS W/ KILL SWITCH. TROUBLESHOOT W/ MECHANICS. RIG DOWN BATCH MIXER, TRANSFER CMT F/ BATCH MIXER TO BULK TANKS. R/D ALL LINES.
2/19/2025	LUNCH BREAK FOR CREW
2/19/2025	WINTERIZE RIG FOR OVERNIGHT TEMPS. SION
2/19/2025	CREW TRAVELED TO CAMP
2/20/2025	CREW TRAVELED TO WBDU 141J
2/20/2025	HTGSM, DISCUSS HAND AND FINGER SAFETY
2/20/2025	CHECK TBG AND CSG PRESSURE "0"
2/20/2025	SET AND TEST COFO "OK"
2/20/2025	(AXIS DOWN TIME) WAIT ON REPLACEMENT PUMP. PUMP ARRIVED ON LOCATION @ 1300HRS
2/20/2025	R/U CMT PUMP, SPOT 20 SX @ 1971 TO 1773 4.7 BBLS, 14.8# 1.32 YIELD. 2%CAL. DISP TO 1773 W/ 6.5 BBLS F/W
2/20/2025	WOC
2/20/2025	RIH TAG TOC @ 1760 W/ 55 JTS. L/D 5 JTS. EOT @ 1610
2/20/2025	R/U CMT PUMP, PLUG 3) SPOT 55SX @ 1610 TO 1066. 12.9 BBLS 14.8# 1.32 YIELD. DISP TO 1066 W/ 4.1 BBLS F/W
2/20/2025	L/D 25 JTS. EOT @ 805
2/20/2025	R/U CMT PUMP PLUG 4) SPOT 20SX @ 810 TO 612 4.7 BBLS 14.8# 1.32 YIELD. DISP TO 612 W/ 2.3 BBLS F/W
2/20/2025	L/D 20 JTS EOT @ 161 W/ 5 JTS.
2/20/2025	WINTERIZE RIG FOR OVER NIGHT TEMPS. SION
2/20/2025	CREW TRAVELED TO CAMP
2/21/2025	CREW TRAVELED TO WBDU 141J
2/21/2025	HTGSM, DISCUSS HAND AND FINGER PLACEMENT.
2/21/2025	CHECK TBG AND CSG PRESSURE "0"
2/21/2025	SET AND TEST COFO "OK"
2/21/2025	R/U CMT PUMP, PLUG 4) SPOT 25SX @ 161, 5.8 BBLS. 14.8# 1.32 YIELD. CIRC CMT TO SURFACE. INSERT LINE THRU BRADEN HEAD. TOP OFF W/ CMT.

2/21/2025	L/D TBG TO "0", RIG DOWN WORKING FLOOR, L/D HANDLING EQ.
2/21/2025	NIPPLE DOWN BOP AND ADAPTER FLANGE.
2/21/2025	VERIFY AND TOP OFF CMT TO SURFACE. M/U WELL HEAD
2/21/2025	RIG DOWN WORK OVER AND PLUGGING PACKAGE.
2/21/2025	LOAD OUT EQ. FOR TRANSPORT. SECURE LOADS.
2/21/2025	LUNCH BREAK FOR CREW

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 439585

CONDITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 439585
	Action Type: [C-103] Sub. Plugging (C-103P)

CONDITIONS

Created By	Condition	Condition Date
mkuehling	No marker - well cut and capped 2/24/2025 - well plugged 2/24/2025	5/1/2025