



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 4/2/25 Operator San Juan Resources API # 30-039-05649

Property Name CLARK #005 Location: Unit E Section 6 Township 24N Range 03W
(Well Name and Number)

Pressure (Shut-in) or Producing) Tubing 45 Intermediate N/A Casing 125 Bradenhead 3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time.	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	125	N/A	N/A	N/A		N/A
10 minutes	0	125	↓	↓	↓		↓
15 minutes	0	125	↓	↓	↓	X	↓
20 minutes	0	125	↓	↓	↓	Y	↓
25 minutes	0	125	↓	↓	↓		↓
30 minutes	0	126					
5 minute SI	2	126					

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 2 Intermediate N/A

REMARKS:

Start Time @ 7:20 End Time @ 7:58 AM
Bradenhead Blew down to nothing under 10 seels had 2 PSI
after shut in time

By Wyatt Templeton Witness _____
Lease Operator
(Position)

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 455010

CONDITIONS

Operator: SAN JUAN RESOURCES, INC. 1499 Blake St, #10C Denver, CO 80202	OGRID: 20208
	Action Number: 455010
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
tvermersch	None	5/7/2025