



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 4-9-2025 Operator Schalk Development API # 30-039-21743
Property Name SCHALK 29-4 #017 Location: Unit I Section 25 Township 29N Range 04W
(Well Name and Number)
Pressure (Shut-in or Producing) Tubing 589 Intermediate NA Casing 589 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate Flowed Flowed	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	Ø	589	N A	N	A	Steady Flow	N A
10 minutes	Ø	589				Surges	
15 minutes	Ø	589				Down to Nothing	
20 minutes	Ø	589				No Flow	
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI	Ø	589				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead Ø Intermediate NA

REMARKS:

STOP CLOCKED PLUNGER WELL, WELL SHUT IN

OPEDED BH- SHORT SOFT PUFF DOWN TO NOTHING IN 4 SECONDS, NO H²S DETECTED (4-CAS MONITOR)

By SCOTT RODGERS Witness _____
LEASE OPERATOR
(Position)

NMOCD Test Area:

1

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 456612

CONDITIONS

Operator: SCHALK DEVELOPMENT CO P.O. Box 25825 Albuquerque, NM 87125	OGRID: 20389
	Action Number: 456612
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
tvermersch	None	5/7/2025