Received by OCD: 8/12/2025 11:02:16 AM

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

	BRADENHEAD TEST REPORT					
Operator SAGUARO PE		30-015-00806				
WEST RED CAKE	roperty Name	Well No.				
7. Surface Location						
UL-Lot Section Township Range	Feet from N/S Line 1980 N	Feet From E/W Line County 1980 E EDDY				
Well Status						
YES YES SHUT-IN	NO INJ SWD OIL	GAS 8/4/25				

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0	/			300
Flow Characteristics					CO2
Puff	(V) N	Y/N/	Y/N	(Y)/ N	WTR_
Steady Flow	Y / (N)	Y/N/	Y //N	Y / (N)	GAS
Surges	Y / (N)	Y/N	y/N	W/N	Type of Flaid Injected for
Down to nothing	W/N	Y/N	Y/N	Y/N	Waterflood if
Gas or Oil	Y / (N)	Ý/N	Y / N	Y/N	applies
Water	Y / N	/ Y / N	Y/N	¥ / (14)	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.
Describe. Please state for each string (A.B.C.D.E) pertinent information regarding bleed down of continuous band up it appears.
Remains - I lease state for
GOOD TEST, NO PRESSURE
Close 10 . 100 . Issued

Signature:	OIL CONSERVATION DIVISION
Printed name: JASW STARWES	Entered into RBDMS
	Re-test
E-mail Address: JASON @ SAGUAROPETROLEUM. COM	
- 1. 701.0705	
Witness. Wardle Lette	

Released to Imaging: 8/13/2025 11:06:36 AM

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 494957

CONDITIONS

Operator:	OGRID:
Saguaro Petroleum, LLC	373933
15 Smith Rd	Action Number:
Midland, TX 79705	494957
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
ronald.heuer	None	8/13/2025