Received by OCD: 8/12/2025 11:03:50 AM

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT API Number Operator Name 30-015-00819 SAGUARO PETROLEUM Well No. Property Name WEST RED LAKE UNIT 7. Surface Location County E/W Line Feet from N/S Line Feet From Township Range UL - Lot Section EDDY 003 27E 121 8 185 Well Status INJECTOR PRODUCER SHUT-IN TA'D WELL GAS SWD OIL NO INJ NO YES YES

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0	/	/		200
Flow Characteristics		/			CO2
Puff	(Y)/ N	Y/N	Y/N/	Ø/ N	WTR
Steady Flow	Y /(N)	Y / N/	Y / N	Y / (N)	GAS _
Surges	Y / (N)	YVN	YN	Y / (N)	Type of Fluid
Down to nothing	(V) N	Y/N	N/N	N	Injected for Waterflood if
Gas or Oil	Y /(N)	/ Y / N	Y / N	Y / N	applies
Water	Y / (N	/ Y / N	/ Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

GOOD TEST, NO TRESSURE

Signature: 0-5	OIL CONSERVATION DIVISION	
Printed name: JASON STARNES	Entered into RBDMS	
Title: SUPERINTENDENT	Re-test :	
E-mail Address: JASON @ SAGUARO PETROLEUM. com	3000	
Date: 8/4/25 Phone: 575-703-9705		
Witness: Word House	No.	
INSTRUCTIONS ON BACK OF T	HIS FORM	

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 494959

CONDITIONS

Operator:	OGRID:
Saguaro Petroleum, LLC	373933
15 Smith Rd	Action Number:
Midland, TX 79705	494959
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
ronald.heuer	None	8/13/2025