

**State Of New Mexico**  
**Energy, Minerals and Natural Resources Department**

---

26-Aug-25

**ROVER OPERATING, LLC**

318 West Adams Street  
10th Floor  
Chicago, IL 60606

**Pre Enforcement Notification**

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the Compliance Officer copied on this letter, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

*INSPECTION DETAIL SECTION*

---

[30-015-02009] HUMBLE #002

OGRID: 371484

L-22-18S-28E 2310 FSL 990 FWL

<b>Inspection Date</b>	<b>Type Inspection</b>	<b>Inspector</b>	<b>Inspection No.</b>
8/26/2025	Routine Inspection	[RZC] Rolando Chavarria	iRZC2523829548
<b>Violation</b>	<b>Title</b>	<b>Corrective Action Due</b>	
cRZC2523855158 19.15.29	Releases Surface Leaks/Spills	11/24/2025	
<i>(TANK LEAKING AROUND THE CHIME )</i>			

---

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

**Note:** Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.