

Sundry Print Report

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

Well Name: INGA 33 FED COM Well Location: T23S / R32E / SEC 33 / County or Parish/State: LEA /

SESE / 32.2546348 / -103.6739393

Well Number: 516H Type of Well: OIL WELL Allottee or Tribe Name:

Lease Number: Unit or CA Name: Unit or CA Number:

INCORPORATED

Subsequent Report

Sundry ID: 2786380

Type of Submission: Subsequent Report

Type of Action: Drilling Operations

Date Sundry Submitted: 04/23/2024 Time Sundry Submitted: 09:53

Date Operation Actually Began: 03/23/2024

Actual Procedure: 3-23-2024 20" Conductor @ 118' 4/1/2024 13 1/2" HOLE 4/1/2024 Surface Hole @ 1,363' MD, 1,363' TVD Casing shoe @ 1,350' MD, 1,349' TVD Ran 10-3/4", 40.5#, J55, BTC Cement w/ 550 sx Class C (1.77 yld, 13.5 ppg), followed by 120 sx Class C (1.36 yld, 14.8 ppg) Test casing at 1,500 psi for 30 min, Circ (90 bbls) 286 sx cement to surface BOP TESTED TO BLM STANDARDS 4/11/2024 9 7/8" HOLE 4/11/2024 Intermediate Hole @ 4,783 MD, 4,769' TVD Casing shoe @ 4,768' MD, 4,754' TVD Ran 8-5/8", 32#, J55, BTC SC (0' - 3,790') Ran 8-5/8", 32#, ECP110, BTC SC (3,790' - 4,768') Cement w/ 470 sx Class C (2.08 yld, 12.7 ppg), followed by 130 sx Class C (1.37 yld, 14.8 ppg) Test casing to 2,239 psi for 30 min, Circ (75 bbls) 202 sx of cement to surface 4/18/2024 7 7/8" HOLE 4/18/2024 Production Hole @ 17,936' MD, 10,509' TVD Casing shoe @ 17,920' MD, 10,509' TVD Ran 5-1/2", 20.0#, EYHCP110, RDT BTX (MJ @ 9,675' & 17,462') Cement w/ 590 sx Class C (3.98 yld, 10.5 ppg), followed by 530 sx Class H (1.60 yld, 13.2 ppg) No casing test , TOC @ 3,165' - Calc , WAITING ON CBL, RR 4/19/2024 Production casing will be tested prior to fracing and reported on the completion sundry.

eceived by OCD: 5/22/2024 9:33:09 AM Well Name: INGA 33 FED COM

Well Location: T23S / R32E / SEC 33 /

SESE / 32.2546348 / -103.6739393

County or Parish/State: LEA?

Well Number: 516H

Type of Well: OIL WELL

Allottee or Tribe Name:

Lease Number:

Unit or CA Name:

Unit or CA Number:

Zip:

US Well Number: 3002549444

Operator: EOG RESOURCES

INCORPORATED

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: EMILY FOLLIS Signed on: APR 23, 2024 09:52 AM

Name: EOG RESOURCES INCORPORATED

Title: Sr. Regulatory Administrator

Street Address: 5509 Champions Drive

City: Midland State: TX

Phone: (432) 848-9163

Email address: emily_follis@eogresources.com

Field

Representative Name:

Street Address:

City: State:

Phone:

Email address:

BLM Point of Contact

BLM POC Name: JONATHON W SHEPARD BLM POC Title: Petroleum Engineer

BLM POC Phone: 5752345972 BLM POC Email Address: jshepard@blm.gov

Disposition: Accepted Disposition Date: 05/01/2024

Signature: Jonathon Shepard

Page 2 of 2

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 346694

CONDITIONS

Operator:	OGRID:
EOG RESOURCES INC	7377
5509 Champions Drive	Action Number:
Midland, TX 79706	346694
	Action Type:
	[C-103] Sub. Drilling (C-103N)

CONDITIONS

Created By		Condition Date
ward.rikala	Adequate cement volume needs to be pumped to achieve the required tie-back for proper zonal isolation.	10/2/2025
ward.rikala	CBL is required post remediation to verify proper zonal isolation below intermediate shoe to TOC.	10/2/2025