



# NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 320-0243  
File Via OCD Permitting

## BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-15-2025 Operator BMG API #30-039-06823

Property Name ERMU Well No. 7 Location: Unit N Section 20 Township 27 Range 1E

Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate      Casing 11 Bradenhead     

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR      FRESH      SALTY      SULFUR      BLACK     

5 MINUTE SHUT-IN PRESSURE BRADENHEAD      INTERMEDIATE     

REMARKS:

no bradenhead, cemented off

By [Signature]  
Lease operator  
(Position)

Witness     

E-mail address

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 516130

CONDITIONS

Operator: BENSON-MONTIN-GREER DRILLING CORP 4900 College Blvd. Farmington, NM 87402	OGRID: 2096
	Action Number: 516130
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
tvermersch	None	12/3/2025