

DESCRIPTION OF THE PROPERTY AND THE PROP

OIL CONSEQUATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD |

AZTEC NM. 87410

(505) 304-6178 FAX: (805) 304-6170

Attp://emard.state.nm.us/ocd/District.NM.distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

	1 7
Date of Test 10 - 30 - 25 Operato	r Wapiti API#30-007-00753
	2 Location: Unit & Section 12 Township 29N Range 18 to
	ibing O Intermediate NA Casing (O Bradenhead
	TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min O 10	Steady Flow
10 min 6 10	Surges
15 min O	Down to Nothing
20 min	Nothing ×
25 min	Gas
30 min	Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions	
CLEAR FRESH SALTY	SULFURBLACK
5 MINUTE SHUT-IN PRESSURE BRADENHEA	D_O INTERMEDIATE NA
REMARKS:	
- Brocken head . O - O - after 5min,	
D-AFTER SIVING	
By Mike Famelli Wir	tness
Operator - ((Position)	
E-mail address	

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 525030

CONDITIONS

Operator:	OGRID:
Wapiti Operating, LLC	328741
1251 Lumpkin Rd	Action Number:
Houston, TX 77043	525030
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By		Condition Date
smcfall	None	12/4/2025