



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 320-0243
File Via OCD Permitting

BRADENHEAD TEST REPORT
(submit 1 copy to above address)

Date of Test 5-17-25 Operator Rim Operating API #30-0 39-05502

Property Name Miller A Well No. 102 Location: Unit 8 Section 13 Township 25 Range 7W

Well Status(Shut-In or Producing) Initial PSI: Tubing _____ Intermediate _____ Casing 65 Bradenhead 8

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Bradenhead	Csg	Int	Csg	
TIME						
5 min	8		LS			
10 min	8		LS			
15 min	8		LS			
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow	_____
Surges	_____
Down to Nothing	_____
Nothing	_____
Gas	_____
Gas & Water	_____
Water	_____

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 8

INTERMEDIATE _____

REMARKS:

By Terry Pearson
Ron Pearson
(Position)

Witness _____

E-mail address _____

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 477787

CONDITIONS

Operator: RIM OPERATING, INC. 5 Inverness Drive East Englewood, CO 80112	OGRID: 372497
	Action Number: 477787
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
jason.heslop	None	12/29/2025