



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 320-0243
File Via OCD Permitting

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-2-25 Operator Kimball API #30-0 39-23058

Property Name Warren Well No. 7 Location: Unit 5 Section 26 Township 25N Range 6W

Well Status(Shut-In or Producing) Initial PSI: Tubing 60 Intermediate — Casing 61 Bradenhead —

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	<u>60</u>		<u>61</u>		
10 min	<u>60</u>		<u>61</u>		
15 min	<u>60</u>		<u>61</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD

INTERMEDIATE

Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 60

INTERMEDIATE ✓ R

REMARKS:

By Terry Pearson

Witness _____

Terry Pearson
(Position)

E-mail address _____

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 471282

CONDITIONS

Operator: KIMBELL OIL CO OF TEXAS 777 Taylor Street Ft Worth, TX 76102	OGRID: 12683
	Action Number: 471282
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
jason.heslop	Test was not marked down to nothing, according to the initial test, the braden head showed 0.	12/29/2025