



# NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1500 R.D. BRAZOS ROAD  
AZTEC NM 87413  
(505) 320-3243  
File Via: OCD Permitting

## BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/9/25 Operator Rim operating API # 30-039-26201  
Property Name Elk Com 10 Well No. 1 Location: Unit H Section 10 Township 25 Range 26  
Well Status (Shut-In or Producing) Initial PSI: Tubing 320 Intermediate      Casing 360 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	<u>0</u>		<u>360</u>			Steady Flow	
10 min	<u>0</u>		<u>360</u>			Surges	
15 min	<u>0</u>		<u>360</u>			Down to Nothing	
20 min						Nothing	<u>/</u>
25 min						Gas	
30 min						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR      FRESH      SALTY      SULFUR      BLACK     

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE     

REMARKS:

By Luke Post

Witness     

Operator  
(Position)

E-mail address LPost@rimop.com

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 478064

CONDITIONS

Operator:  RIM OPERATING, INC. 5 Inverness Drive East Englewood, CO 80112	OGRID:  372497
	Action Number:  478064
	Action Type:  [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
jason.heslop	None	12/29/2025