



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87411
(505) 320-3243
File Via OCD Permitting

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/12/25 Operator Rim operating API # 30-039-24213
Property Name Elk 60 m 10 Well No. 1C Location: Unit F Section 10 Township 25N Range 2W
Well Status (Shut-In or Producing) Initial PSI: Tubing 60 Intermediate Casing 120 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	0		120			Steady Flow	
10 min	0		120			Surges	
15 min	0		120			Down to Nothing	
20 min						Nothing	
25 min						Gas	
30 min						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

By Luke Post

Witness

operator
(Position)

E-mail address LPost@rimop.com

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 478074

CONDITIONS

Operator: RIM OPERATING, INC. 5 Inverness Drive East Englewood, CO 80112	OGRID: 372497
	Action Number: 478074
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
jason.heslop	None	12/29/2025