

BRADENHEAD TEST REPORT							
(submit 1 copy to above address)							
Date of Test		Operator		API #			
12-4-23		Simcoe		30-0 45-34144			
Property Name		Well No.		Location: Unit			
NEBU		346		9 Section 36 Township 31N Range 8E			
Well Status (Shut- <u>in</u> or <u>Producing</u>)		Initial PSI: Tubing		Intermediate			
Shut- <u>in</u>		NA		13			
Casing		∅		Bradenhead			
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH							
PRESSURE							
Testing	Bradenhead			INTERM		FLOW CHARACTERISTICS	
	BH	Int	Csg	Int	Csg		BRADENHEAD
TIME							
5 min	—	12	∅	—	∅	Steady Flow	
10 min	—	12	∅	—	∅	Surges	
15 min	—	12	∅	—	∅	Down to Nothing	
20 min						Nothing	
25 min						Gas	
30 min						Gas & Water	
						Water	
If bradenhead flowed water, check all of the descriptions that apply below:							
CLEAR <input type="checkbox"/> FRESH <input type="checkbox"/> SALTY <input type="checkbox"/> SULFUR <input type="checkbox"/> BLACK <input type="checkbox"/>							
5 MINUTE SHUT-IN PRESSURE			BRADENHEAD		INTERMEDIATE		
REMARKS: Nothing on BH when opened - nothing on BH after 5min shut in - had blow to nothing in 1min 12sec - Nothing on int after 5min shut in -							
By ICAV Rep: Ernie C.			Witness: <u>John</u>				
(Position)							
E-mail address							

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 437772

CONDITIONS

Operator: SIMCOE LLC 1199 Main Ave., Suite 101 Durango, CO 81301	OGRID: 329736
	Action Number: 437772
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
jason.heslop	None	12/31/2025