



**NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT
(Submit 2 copies to above address)

Date of Test 4-10-2025 Operator Schalk Development API # 30-039-20085

Property Name CINCO DIABLOS #009 Location: Unit 1 Section 8 Township 25N Range 07W
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 24 Intermediate X Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	0					
10 minutes	0	0	X				
15 minutes	0	0					
20 minutes							
25 minutes							
30 minutes							
5 minute SI	0	0					

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate _____

REMARKS:

BH had 0 psi on it.

Casing pressure was 103 in 2002.

By Caleb Spelling Witness _____
pumper

(Position)

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 455218

CONDITIONS

Operator: SCHALK DEVELOPMENT CO P.O. Box 25825 Albuquerque, NM 87125	OGRID: 20389
	Action Number: 455218
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
jason.heslop	None	1/5/2026