



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District_III/3district.htm

BRADENHEAD TEST REPORT
(submit 1 copy to above address)

Date of Test 5-22-25 Operator: High River Res Operating, LLC API #30-039-06095

Property Name: Fred Phillips A Well No. 1A Location: Unit: A Section: 10 Township: 25N Range: 3W

Well Status(Shut-In or Producing) Initial PSI: Tubing 52 Intermediate Casing 51 Bradenhead 22

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	BH	Bradenhead	INTERM			
TIME	Int	Csg	Int	Csg		
5 min	0	(51			
10 min	0		51			
15 min	0		51			
20 min	0		51			
25 min	0		51			
30 min	0		51			

FLOW CHARACTERISTICS
BRADENHEAD **INTERMEDIATE**

Steady Flow	
Surges	
Down to Nothing	X
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

Blew down in 5 sec.

By Bill Julian

Witness

(Position)

E-mail address

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 468442

CONDITIONS

Operator: High River Resources Operating, LLC 2700 Farmington Ave FARMINGTON, NM 87401	OGRID: 328985
	Action Number: 468442
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
jason.heslop	The testing shows the braden head pressure was at 22 pounds and blew down in 5 seconds. Please monitor this wells braden head for pressure issue's.	1/7/2026