



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District_III/3district.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 05/29/2025 Operator: High River Res Operating, LLC API #30-039-22327

Property Name: Reames A Well No. 1E Location: Unit: J Section: 24 Township: 26N Range: 6W

Well Status(Shut-In or Producing) Initial PSI: Tubing 75 Intermediate _____ Casing 75 Bradenhead 24

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			FLOW CHARACTERISTICS		
	BH	Bradenhead	INTERM	BRADENHEAD	INTERMEDIATE	
5 min	<u>191bs</u>	<u>73</u>				
10 min	<u>161bs</u>	<u>73</u>				
15 min	<u>161bs</u>	<u>73</u>				
20 min	<u>161bs</u>	<u>73</u>				
25 min	<u>141bs</u>	<u>72</u>				
30 min	<u>131bs</u>	<u>72</u>				

	BRADENHEAD	INTERMEDIATE
Steady Flow	<input checked="" type="checkbox"/>	
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 161bs INTERMEDIATE _____

REMARKS:

Opened bradenhead, 241bs of pressure, blew 30 minutes, had 131bs steady flow, afterwards, shut in for 30 minutes, pressure built back up to 221bs.

By Logan Petago

Witness _____

Lease operator
(Position)

E-mail address lpetago@highriverllc.com

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 469205

CONDITIONS

Operator: High River Resources Operating, LLC 2700 Farmington Ave FARMINGTON, NM 87401	OGRID: 328985
	Action Number: 469205
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
jason.heslop	This well needs a gas sample on the braden head. The well file shows very little pressure on the braden head until 2022 where is showed 5 pounds but has increased to 24# in 2025. Please continue to monitor the braden head. According to the braden head test, it had a constant flow and increased back up during the 5-minute shut in.	1/7/2026