

District 2 Artesia

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Solanis		API Number 30-015-42348	
Property Name Pine Springs 2 State SWD #1			Well No. #1

Surface Location									
UL - Lot K	Section 2	Township 24	Range 25E	Feet from 2500	N/S Line S	Feet From 2500	E/W Line W	County Eddy	

Well Status							DATE
YES	TA'D WELL (NO)	YES	SHUT-IN (NO)	INJ	INJECTOR (SWD)	OIL	PRODUCER GAS 6-19-25

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	Cemented	Cemented		Zero	Zero
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / (N)	CO2 <input type="checkbox"/>
Steady Flow	Y / N	Y / N	Y / N	Y / (N)	WTR <input checked="" type="checkbox"/>
Surges	Y / N	Y / N	Y / N	Y / (N)	GAS <input type="checkbox"/>
Down to nothing	Y / N	Y / N	Y / N	(Y) / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / N	Y / N	Y / N	Y / (N)	
Water	Y / N	Y / N	Y / N	Y / (N)	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Michael Ortiz	OIL CONSERVATION DIVISION
Printed name: Michael Ortiz	Entered into RBDMS
Title: Well site Supervision	Re-test
E-mail Address: M.Ortiz27@yahoo.com	
Date: 6-19-25	Phone: 432-664-6483
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 477120

CONDITIONS

Operator: SOLARIS WATER MIDSTREAM, LLC 9950 WOODLOCH FOREST DR THE WOODLANDS, TX 77380	OGRID: 371643
	Action Number: 477120
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
ronald.heuer	None	1/30/2026