

District I
 1625 N French Dr., Hobbs, NM 88240
 Phone (575) 393-6161 Fax. (575) 393-0120

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name MORNINGSTAR OPERATING, LLC	API Number 30-025-31704
Property Name VACUUM GLORIETA WEST UNIT	Well No 64

Surface Location									
UL - Lot	Section	Township	Range	Feet from	NS Line	Feet From	E/W Line	County	
E	36	17S	34E	1484	FNL	204	FWL	LEA	

Well Status								DATE			
TA'D WELL	YES	NO	SHUT-IN	YES	NO	INJECTOR	SWD	OIL	PRODUCER	GAS	
YES		<input checked="" type="checkbox"/>	YES		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>					4-1-2025

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod. Casing	(E)Tubing
Pressure	0			0	0
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.
 Well is on vacuum.

Signature:	OIL CONSERVATION DIVISION
Printed name: Eloy Carranza	Entered into RBDMS
Title: BSA	Re-test
E-mail Address: emillon@ctfield5165.com	
Date: 4-1-2025	
Phone: 682-478-6751	
Witness	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 464515

CONDITIONS

Operator: MorningStar Operating LLC 400 W 7th St Fort Worth, TX 76102	OGRID: 330132
	Action Number: 464515
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
rolando.chavarria	None	1/30/2026