

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name Stephens + Johnson Operating Co.	API Number 30-015-02245
Property Name East Millman Unit	Well No 143

Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
K	14	19S	28E	1980	FSL	1980	FWL	Eddy

Well Status

TA'D Well	SHUT-IN	INJECTOR	PRODUCER	DATE
YES (NO)	YES (NO)	(INJ) SWD	OIL GAS	7/29/2025

OBSERVED DATA

	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing		
Pressure	0	/	/		880		
Flow Characteristics							
Puff	Y/N (Y)			Y/N	Y/N	(Y) N	CO2 _____
Steady Flow	Y/N (Y)			Y/N	Y/N	Y/N (Y)	WTR _____
Surges	Y/N (Y)			Y/N	Y/N	Y/N (Y)	GAS _____
Down to nothing	(Y) N			Y/N	Y/N	(Y) N	If applicable type
Gas or Oil	Y/N (Y)			Y/N	Y/N	Y/N (Y)	fluid injected for
Water	Y/N (Y)	Y/N	Y/N	Y/N (Y)	Waterflood		

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

BHT-OK

REC'D AUG 04 2025

Signature: <i>Mark Hope</i>	OIL CONSERVATION DIVISION
Printed name: Mark Hope	Entered RBDMS
Title: Pumper	Re-test
E-mail Address: hope-mark53@yahoo.com	
Date:	Phone: 575-748-5629
Witness: <i>Conrad Hope</i>	

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 492803

CONDITIONS

Operator: STEPHENS & JOHNSON OP CO P.O. Box 2249 Wichita Falls, TX 76307	OGRID: 19958
	Action Number: 492803
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
ronald.heuer	None	2/3/2026