

State of New Mexico  
 Energy, Minerals and Natural Resources Department  
 Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name <b>Stephens + Johnson Operating Co.</b>	API Number <b>30-015-02231</b>
Property Name <b>East Millman Pool Unit Tract 7</b>	Well No <b>4</b>

Surface Location

U.L. - Lot <b>L</b>	Section <b>13</b>	Township <b>19S</b>	Range <b>28E</b>	Feet from <b>2310</b>	N/S Line <b>FSL</b>	Feet From <b>660</b>	E/W Line <b>FWL</b>	County <b>Eddy</b>
------------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	-------------------------	------------------------	-----------------------

Well Status

TA'D Well YES <input type="radio"/> NO <input checked="" type="radio"/>	SHUT-IN YES <input type="radio"/> NO <input checked="" type="radio"/>	INJECTOR <input checked="" type="radio"/> INJ SWD	PRODUCER OIL GAS	DATE <b>7/29/2025</b>
--	--	--	---------------------	--------------------------

OBSERVED DATA

	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure	<b>0</b>			<b>0</b>	<b>520</b>
Flow Characteristics					
Puff	Y/ <input checked="" type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input checked="" type="radio"/> N	CO2 _____
Steady Flow	Y/ <input checked="" type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input checked="" type="radio"/> N	WTR _____
Surges	Y/ <input checked="" type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input checked="" type="radio"/> N	GAS _____
Down to nothing	<input checked="" type="radio"/> Y <input type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	<input checked="" type="radio"/> Y <input type="radio"/> N	If applicable type
Gas or Oil	Y/ <input checked="" type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input checked="" type="radio"/> N	fluid injected for
Water	Y/ <input checked="" type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	Y/ <input checked="" type="radio"/> N	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

**BHT - OK**

REC'D AUG 04 2025

Signature: <b>Mark Hope</b>	OIL CONSERVATION DIVISION
Printed name: <b>Mark Hope</b>	Entered RBDMS
Title: <b>Pumper</b>	Re-test
E-mail Address: <b>hope-mark53@yahoo.com</b>	
Date:	Phone: <b>575-748-5629</b>
Witness: <b>Donald Allen</b>	

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 493048

**CONDITIONS**

Operator: STEPHENS & JOHNSON OP CO P.O. Box 2249 Wichita Falls, TX 76307	OGRID: 19958
	Action Number: 493048
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

**CONDITIONS**

Created By	Condition	Condition Date
ronald.heuer	None	3/20/2026