

12/20/2025  
South District - Artesia

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

**BRADENHEAD TEST REPORT**

Operator Name <b>BCE-Mach</b>		API Number <b>30.025-01218</b>
Property Name <b>Saunders Saltwater Disposal</b>		Well No. <b>2</b>

**Surface Location**

UL - Lot <b>N</b>	Section <b>3</b>	Township <b>155</b>	Range <b>33 E</b>	Feet from <b>810</b>	N/S Line <b>S</b>	Feet From <b>1980</b>	E/W Line <b>W</b>	County <b>Lea</b>
----------------------	---------------------	------------------------	----------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

**Well Status**

TA'D WELL YES <input type="radio"/> NO <input checked="" type="radio"/>	SHUT-IN YES <input type="radio"/> NO <input checked="" type="radio"/>	INJ <input type="radio"/>	INJECTOR <input checked="" type="radio"/> (SWD)	PRODUCER OIL <input type="radio"/> GAS <input type="radio"/>	DATE <b>12/4/2021</b>
--	--	------------------------------	--	---	--------------------------

**OBSERVED DATA**

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	<b>0</b>	/	/	<b>260</b>	<b>700</b>
Flow Characteristics					
Puff	Y <input checked="" type="radio"/> N <input type="radio"/>	Y / N	Y / N	Y / N	CO2 <input type="checkbox"/>
Steady Flow	Y / N <input checked="" type="radio"/>	Y / N	Y / N	<input checked="" type="radio"/> Y / N	WTR <input checked="" type="checkbox"/>
Surge	Y / N <input checked="" type="radio"/>	Y / N	Y / N	Y / N <input checked="" type="radio"/>	GAS <input type="checkbox"/>
Down to nothing	<input checked="" type="radio"/> Y / N	Y / N	Y / N	Y / N <input checked="" type="radio"/>	Type of fluid injected for Waterflood if applies
Gas or Oil	Y / N <input checked="" type="radio"/>	Y / N	Y / N	Y / N <input checked="" type="radio"/>	
Water	Y <input checked="" type="radio"/> N <input type="radio"/>	Y / N	Y / N	Y <input checked="" type="radio"/> N <input type="radio"/>	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

**BHT - Failed**  
Bled prod csg down to 0 in 20 mins - closed valve  
built press back - well must be shut in ASAP

Signature:	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date:	
Phone:	
Witness: <b>[Signature]</b>	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/oecd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 533912

**CONDITIONS**

Operator: BCE-Mach III LLC 14201 Wireless Way, STE 300 Oklahoma City, OK 73134	OGRID: 333695
	Action Number: 533912
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

**CONDITIONS**

Created By	Condition	Condition Date
pgoetze	None	3/20/2026