

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
May 27, 2004

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-007-20851
1. Type of Well: Oil Well Gas Well ☒ Other ☐ Coalbed Methane		5. Indicate Type of Lease STATE ☐ FEE ☒
2. Name of Operator EL PASO E & P COMPANY, L.P.		6. State Oil & Gas Lease No.
3. Address of Operator PO BOX 190, RATON, NM 87740		7. Lease Name or Unit Agreement Name VPR A
4. Well Location Unit Letter B : 1232 feet from the North line and 1794 feet from the East line Section 29 Township 31N Range 20E NMPM Colfax County		8. Well Number 455
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 8,173' (GL)		9. OGRID Number 180514
Pit or Below-grade Tank Application ☐ or Closure ☐		
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____		
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐ Completion ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

08/17/07 Superior ran Cement Bond Log. Estimated top of cement at 458'.
08/25/07 Pulled 5 1/2" casing slips. RIH 1" pipe. Pumped 64 sks cement down hole. Circulated cement to pit. ✓
08/27/07 Superior ran Cement Bond Log. Estimated top of cement at surface. ✓
03/01/08 Weatherford Wireline perf'd 1st stage - 1980'- 1983', 1996'- 1999' 24 Holes
HES frac'd 1st stage - Pumped 235,841 scf 70% quality nitrogen foam with 25# linear gel and 11,023 lbs 20/40 mesh sand.
Perf'd 2nd stage - 1057'- 1060', 1081'- 1084', 1119'- 1122' 36 Holes
Frac'd 2nd stage - Pumped 206,233 scf 70% quality nitrogen foam with 25# linear gel and 15,692 lbs 20/40 mesh sand.
Perf'd 3rd stage - 944'- 953', 984'- 987', 1000'- 1003', 1013'- 1017' 84 Holes
Frac'd 3rd stage - Pumped 295,246 scf 70% quality nitrogen foam with 25# linear gel and 41,415 lbs 20/40 mesh sand.
Perf'd 4th stage - 804'- 811', 837'- 840' 40 Holes
Frac'd 4th stage - Pumped 283,904 scf 70% quality nitrogen foam with 25# linear gel and 21,210 lbs 20/40 mesh sand.
03/08/08 Coil tubing clean out.
03/18/08 RIH tubing, rods and pump. Well is ready to be tested and put on production. ✓

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Shirley Mitchell TITLE Regulatory Analyst DATE 06/06/2008
Type or print name Shirley A Mitchell E-mail address: shirley.mitchell@elpaso.com Telephone No. (505) 445-6785

For State Use Only

APPROVED BY: Ed Martin TITLE DISTRICT SUPERVISOR DATE 6/10/08
Conditions of Approval (if any):