


**BURNETT OIL CO.  
JACKSON B #32  
API 30-015-22621  
1980/S 1980/E SECT. 1 TWS. 17 S., RNG. 30 E.  
WATER FLOW REMEDIATION**


**WORKPLAN**



**Prepared By  
Eddie Seay Consulting  
July 2011**

July 12, 2011

NMOCD, District II  
ATTN: Mike Bratcher  
811 South First St.  
Artesia, NM 88210



RE: Burnett Oil Co. Inc.  
Jackson B #32  
API 30-015-22621

Mr. Bratcher:

As required, a work plan is attached to remediate the water flow spill. A C-141 was filed earlier. When approved, we will make plans for the work.

We are filing the attached work plan to remediate the area.

Copies are being sent to James Amos with BLM. Should you have any questions, please call.

Sincerely,

A handwritten signature in black ink, appearing to read "Eddie W. Seay". The signature is fluid and cursive, with a long, sweeping underline that extends to the right.

Eddie W. Seay, Agent  
Eddie Seay Consulting  
601 W. Illinois  
Hobbs, NM 88242  
575-392-2236  
[seay04@leaco.net](mailto:seay04@leaco.net)

cc: Burnett Oil  
cc: BLM, James Amos

# **WORKPLAN**

## **General:**

A C-141 was filed and BLM and OCD was notified of the water flow. Will repair well and remediate spill area.

## **Groundwater:**

According to State Engineer and groundwater information, the depth of water occurs at approximately 300 feet below surface.

## **Remediation Proposal:**

Our cleanup will be to excavate contaminated soil, haul to an OCD approved facility and replace with clean soil and seed. Before backfilling, the area will be tested for TPH, BTEX and Chloride to assure we meet OCD guidelines, and only after OCD and BLM approve, we will backfill and level.

The OCD and BLM will be notified of all activities and a report will be filed upon completion.

## **Ranking Criteria Score: O**

This site has a 5000 ppm TPH cleanup and will cleanup BTEX and Chloride per OCD.

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Burnett Oil Co. Inc.	Contact	Bellon Matthews
Address	Box 198 Loco Hills NM 98255	Telephone No.	575-147-2313
Facility Name	Jackson B # 32	Facility Type	Ing. Well
Surface Owner	BLM	Mineral Owner	
		Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	1	17	30	1980	South	1980	East	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release	Salt Water	Volume of Release	App. 2000 lbs	Volume Recovered	300 lbs
Source of Release	Casing Leak	Date and Hour of Occurrence	7/4	Date and Hour of Discovery	7/5 9am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bralcher - OED Jim Ayres - BLM		
By Whom?	Eddie Seay - Agent	Date and Hour	7/5 9:15 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Hole in casing causing injection water to come to surface, and into pasture  
shot in injection, vacuum up water, build emergency pit to catch water,  
also put track tank to hold water. Waiting on Pilling unit to repair well.

Describe Area Affected and Cleanup Action Taken.\*

Ran into pasture south & west; water pooled up in low spot approx 125 ft  
south. area (110x80) water soaked. Ran water in small drain, 204 ft wide  
approx 150 ft. All available water vacuumed up. (will file Work Plan for remediation)

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Eddie W Seay</u>		OIL CONSERVATION DIVISION	
Printed Name: <u>Eddie W Seay</u>		Approved by District Supervisor:	
Title: <u>Agent</u>	Approval Date:	Expiration Date:	
E-mail Address: <u>seay@edloco.net</u>	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: <u>7/7/2011</u>	Phone: <u>575-390-2454</u>		

\* Attach Additional Sheets If Necessary

